

ASSIGNMENT

From: _____ Date: _____
 Est: _____
 OD / TP RES / CD RES / EVA / INV / MV
 To in Vehicle No: _____
 at Work / Home / Other
 of _____
 Insured: _____
 Policy No: _____
 Claim No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Vehicle: _____
 (Policy Condition)

N/S	O/S

Remark: The vehicle had commenced its
 repair at the time of inspection.

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMZ9621H Yr Regn: 2016, June
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Bmw 216D C.D. 1496

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 401861 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WBA2E320005B45034

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/45R17

R: 225/45R17

ES / DUN / EXNOVA / GY / FS / L / IZA / MIG / QHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

R/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

Rear

R/Bal. 06 mm

L/Bal. 06 mm

D.O.I.

28/10/24

Survey held at

Xin Hua

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TRAIG

COE Expiry: _____

Estimate given during: Yes ()

1st Survey: No ()

MV:

PV:

Nett:

Date/Time, File Pass to?

☐ : Preli. Report

1) _____

☐ : Final Report

Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

S + R.S. \$1

Photos

Others

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Insp (\$ _____)

Report Form: _____

Report Form: _____