

ASS. REC. BY:

REF:

LIP/

CS/Lip 24100099/knp3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

847K

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

4

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

G8J9042T

Yr Regn:

09.19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

NIS NV200

c.c

1461

Colour

White

A/C:

Insured / Std / NI / NA

Sp. Reading

120811

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

VSKYBAN208.0179251

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: M / S/Rim / STD A/Rim or

Tyre Size:

F:

175T70R14

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Falken

Front

Rear

R/Bal.

J

mm

R/Bal.

9

mm

L/Bal.

P

mm

L/Bal.

9

mm

D.O.A.

24/9/24

D.O.I.

2/10/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

7/10 2/1 Pmp 834501. Calm (Red. \$6072.78, 63%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. SI

Fuel

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	01/10/2024 10:44 (SGT)
Reported by	Actual Driver
Date of Accident	24/09/2024 07:20 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	JUNCTION OF WOODLANDS AVE 7 AND WOODLANDS ST 83
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBJ9042T
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	UNITED TECH ENGINEERING PTE LTD
Company Reg No	199602127N
Email Address	ute@ute.com.sg
Mobile Phone No	(Phone) +65-64833693
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Nissan
Model	Nv200
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	1461
Vehicle Fuel	-
First Registration Date	-
Chassis no	-
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	Great Eastern General Insurance Limited
Policy Number / Cover Note Number	V0113462

DRIVER

Name of Driver	MYO SWE TUN
NRIC No	S2727778J
Date Of Birth	17/03/1966
Occupation	Outdoor
Driving Pass Date	02/09/2000
Driving License Pass Class	3
Driving License Validity	Valid
Driving experience	24 YEARS
Gender	Male
Mobile Number	(Phone) +65-88149398
Alt. Phone Number	-
Email Address	david@ute.com.sg
Address	BLK 706 JURONG WEST ST 71 #08-68
Address complement	-
Postcode	640706
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

PASSENGER 1

Name	MARY CHIN
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO SKETCH PLAN.

NOTE: VEHICLE REPAIR AT OWNER W/SHOP

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	PA8998Z
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Bus
Name of Driver	MUSTAPAH BIN MOHAMED
-	S1726191F
Contact Number	(Phone) +65-96473204
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-



SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

3. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time




Driver's Signature (If driver is not the policyholder) / Date & Time






Witnessed by Reporting Centre Personnel



Sketch Plan



Describe Circumstances of the Accident

While ALT 78421 stopped on mobile lane
at junction of Woodlands Ave & Woodlands St 83
when traffic light RPA 84782 hit
from back.

Declaration


We declare the foregoing particulars are true in every respect.


Policyholder's Signature
Time




Driver's Signature (If driver is not the policyholder) / Date
Time




Witnessed by Reporting Centre
Personnel

源摩哆廠

GUAN MOTOR WORKS

Business Regn. No: 08102600F

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

REPAIR ESTIMATE GBJ9042T

NOT Notified
C/Rep & 3450h
Recovery After Paim
4 days

No.	Qty	Nett Items			
1	1	Rear bumper	Ref/CM	\$ 595.20	✓
2	2	Rear bumper side retainer	\$ R	140.80	X
3	2	Rear bumper reflector	\$ R	191.60	X
4	1 set	Rear bumper clips	\$ M	50.00	✓
5	1	Rear bumper inner foam	\$ CM	124.70	✓
6	1	Rear LH tailgate	Ref/CM	1,967.80	✓
7	1	Rear LH tailgate outer handle	MJ \$CM	351.50	✓
8	1	Rear LH tailgate "NISSAN" LOGO	\$ M	52.50	✓
9	1	Rear LH tailgate "NV 200" emblem	\$ R	86.40	✓
10	1	Rear LH tailgate lower lock	\$ R	166.10	X
11	1	Rear LH tailgate top lock	\$ R	186.10	X
12	1	Rear RH tailgate	R \$M	1,753.70	X
13	1	Rear RH tailgate rubber	\$ R	351.50	X
14	1	Rear RH tailgate lower lock	\$ R	166.10	X
15	1	Rear RH tailgate top lock	\$ R	186.10	X
16	1 set	Rear tailgate inner trim board clips	\$ M	80.00	✓
17	1	Rear tailgate weatherstrip	\$ R	79.10	X
18	1	Rear end panel	\$ R	385.00	X
				\$ 6,914.20	
			Less 10%	\$ 691.42	
			Total :	\$ 6,222.78	
			LKK Auto Consultants will not be liable for the Repeater of the following:		
			- To resurvey before/after spray painting - To display damaged part(s) during resurvey - Prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		
19	1	Rear LH tailgate "70km/h" sticker	\$ R	15.00	✓
20	1	Rear RH tailgate "6pax" sticker	\$ R	15.00	✓
21	1	Rear number plate	\$ R	50.00	X
22	1 set	Reverse sensors	\$ CM	280.00	2005N
23	1 set	Rear end panel sealant	\$ NN	60.00	X
24	2 set	Rear windscreen sealant	\$ M	100.00	405N-
			Acknowledged by Repeater	\$	
			Signature:	\$	
			Date:	\$	
			Total :	\$ 520.00	
			<u>Labour</u>		
1		Labour Charges for remove/refit, panel beating, cutting welding and replacement of damages.	\$	1,000.00	5001
2		To putty and spray Spray Paintings charges.	\$	1,200.00	400d
3		To remove, refit both rear tailgate windscreen glass.	\$	240.00	801
4		To check wirings and lightings.	\$	40.00	151.
5		To remove, transfer both tailgate fittings.	\$	120.00	601
6		To replace reverse sensors.	\$	80.00	501
7		To apply anti rust treatment	\$	100.00	301
			Total :	\$ 2,780.00	
			Total Parts and Labour :	\$ 9,522.78	