SW0E246F0003 / WAH HONG MOTORS & CREDIT PTE LTD ENTRY DATE & TIME: 15/06/2024 13:24 (SGT) SUBMITTED BY: Wee Pauline VERSION: 1 (15/06/2024 13:24 (SGT))



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission 15/06/2024 13:24 (SGT) Reported by Both Policyholder and Actual Driver Date of Accident 14/06/2024 15:30 (SGT) Exact Location of Accident Near Kheam Hock Rd, Kheam Hock Park, Singapore Additional Location Information PIE TOWARDS TUAS NEAR ADAM RD EXIT Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SJU3296P

INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner S ROSNAHNI BTE TUGIRAN NRIC No SXXXX421H Email Address ROSNAHNITUGIRAN67@GMAIL.COM Mobile Phone No (Phone) +65-97658821 Alternative Phone No

VEHICLE PARTICULARS

Manufacturer Kia Model Cerato Variant **FORTE** Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to

No - Claiming third party your vehicle? Vehicle Category Private car

Transmission Auto CC 1591

INSURANCE COMPANY

Name of Insurance Company Direct Asia Insurance (Singapore) Pte Ltd Policy Number / Cover Note Number MT/00866722/03

DRIVER

Name of Driver S ROSNAHNI BTE TUGIRAN NRIC No SXXXX421H Date Of Birth 19/09/1967 Occupation Indoor

Driving Pass Date Driving experience Gender Mobile Number Alt. Phone Number Email Address Address Address Address complement Postcode s the driver the policyholder? f No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Wehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver	19/10/2007 16 YEARS AND 8 MONTHS Female (Phone) +65-97658821 - ROSNAHNITUGIRAN67@GMAIL.COM BLK 164, BUKIT BATOK ST 11 #07-134 650164 Yes - No
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident Weather Conditions Road Surface	Chain Collision Clear Wet
OTHER INFORMATION	
Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Franslator's name Franslator's ID Franslator's phone number Franslator's email Original language used in the statement	
DETAILS OF POLICE ACTION	
Was the accident reported to the police? Was notice of intended Prosecution given?	No No

CIRCUMSTANCES OF ACCIDENT

If yes, against whom?

On 14th June 2024, at approximately 1530hrs, I was driving my vehicle (SJU3296P) along the PIE towards Tuas near Adam Road. Suddenly, the vehicle in front of me came to an abrupt stop. I managed to stop my vehicle in time to avoid colliding with the vehicle ahead.

Shortly after stopping, I felt an impact from the rear of my vehicle, followed by a second impact. These two impacts pushed my vehicle forward, causing it to collide with the vehicle in front of me. Unfortunately, I did not get the licence plate number of the vehicle in front.

- I exited my vehicle to assess the situation.
- The driver of the vehicle in front, which my vehicle collided with, also exited and inspected his car.
- The driver of the front vehicle indicated that the damage to his car was not serious and decided to leave the scene without further action.
- I observed that Vehicle B (SNH520H) had collided with the rear of my vehicle, and Vehicle C (YQ1373G) was the last vehicle in the sequence.
- No injuries were reported by any of the drivers or passengers at the scene.
- We documented the scene by taking several photographs of the vehicles and their positions.
- After documenting the scene, all parties left the area.

ATTACHMENT(S)

Are accident photos available for attachment? Yes

DETAILS OF OTHER VEHICLE PROPERTY 1

SNH520H
-
-
-
-
Private car
-
(Phone) +65-85712789
-
-
-
China Taiping Insurance (Singapore) Pte. Ltd.
-
-
-

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour	YQ1373G - - -
Vehicle Category	- Commercial vehicle
Name of Driver	-
Contact Number	(Phone) +65-93214584
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number	UNKNOWN
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	(Phone) +65-87643554
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	_

On 14th June 2024, at approximately 1530hrs, I was driving my vehicle (SJU3296P) along the PIE towards Tuas near Adam Road. Suddenly, the vehicle in front of me came to an abrupt stop. I managed to stop my vehicle in time to avoid colliding with the vehicle ahead. Shortly after stopping. I felt an impact from the rear of my vehicle, followed by a second impact. These two impacts pushed my vehicle forward, causing it to collide with the vehicle in front of me. Unfortunately, I did not get the licence plate number of the vehicle in front. - I exited my vehicle to assess the situation. - The driver of the vehicle in front, which my vehicle collided with, also exited and inspected his car. - The driver of the front vehicle indicated that the damage to his car was not serious and decided to leave the scene without further action. - I observed that Vehicle B (SNH520H) had collided with the rear of my vehicle, and Vehicle C (YQ1373G) was the last vehicle in the sequence. - No injuries were reported by any of the drivers or passengers at the scene. - We documented the scene by taking several photographs of the vehicles and their positions. - After documenting the scene, all parties left the area.	PIE towards Tuas near Adam Road. Suddenly, the vehicle in front of me came to an abrupt stop. I managed to stop my vehicle in time to avoid colliding with the vehicle ahead. Shortly after stopping, I felt an impact from the rear of my vehicle, followed by a second impact. These two impacts pushed my vehicle forward, causing it to collide with the vehicle in front of me. Unfortunately, I did not get the licence plate number of the vehicle in front. - I exited my vehicle to assess the situation. - The driver of the vehicle in front, which my vehicle collided with, also exited and inspected his car. - The driver of the front vehicle indicated that the damage to his car was not serious and decided to leave the scene without further action. - I observed that Vehicle B (SNH520H) had collided with the rear of my vehicle, and Vehicle C (YQ1373G) was the last vehicle in the sequence. - No injuries were reported by any of the drivers or passengers at the scene. - We documented the scene by taking several photographs of the vehicles and their positions.	ribe Circumstance of the Accident	
PIE towards Tuas near Adam Road. Suddenly, the vehicle in front of me came to an abrupt stop. I managed to stop my vehicle in time to avoid colliding with the vehicle ahead. Shortly after stopping, I felt an impact from the rear of my vehicle, followed by a second impact. These two impacts pushed my vehicle forward, causing it to collide with the vehicle in front of me. Unfortunately, I did not get the licence plate number of the vehicle in front. - I exited my vehicle to assess the situation. - The driver of the vehicle in front, which my vehicle collided with, also exited and inspected his car. - The driver of the front vehicle indicated that the damage to his car was not serious and decided to leave the scene without further action. - I observed that Vehicle B (SNH520H) had collided with the rear of my vehicle, and Vehicle C (YQ1373G) was the last vehicle in the sequence. - No injuries were reported by any of the drivers or passengers at the scene. - We documented the scene by taking several photographs of the vehicles and their positions.	PIE towards Tuas near Adam Road. Suddenly, the vehicle in front of me came to an abrupt stop. I managed to stop my vehicle in time to avoid colliding with the vehicle ahead. Shortly after stopping, I felt an impact from the rear of my vehicle, followed by a second impact. These two impacts pushed my vehicle forward, causing it to collide with the vehicle in front of me. Unfortunately, I did not get the licence plate number of the vehicle in front. - I exited my vehicle to assess the situation The driver of the vehicle in front, which my vehicle collided with, also exited and inspected his car The driver of the front vehicle indicated that the damage to his car was not serious and decided to leave the scene without further action I observed that Vehicle B (SNH520H) had collided with the rear of my vehicle, and Vehicle C (YQ1373G) was the last vehicle in the sequence No injuries were reported by any of the drivers or passengers at the scene We documented the scene by taking several photographs of the vehicles and their positions After documenting the scene, all parties left the area.		
PIE towards Tuas near Adam Road. Suddenly, the vehicle in front of me came to an abrupt stop. I managed to stop my vehicle in time to avoid colliding with the vehicle ahead. Shortly after stopping, I felt an impact from the rear of my vehicle, followed by a second impact. These two impacts pushed my vehicle forward, causing it to collide with the vehicle in front of me. Unfortunately, I did not get the licence plate number of the vehicle in front. - I exited my vehicle to assess the situation The driver of the vehicle in front, which my vehicle collided with, also exited and inspected his car The driver of the front vehicle indicated that the damage to his car was not serious and decided to leave the scene without further action I observed that Vehicle B (SNH520H) had collided with the rear of my vehicle, and Vehicle C (YQ1373G) was the last vehicle in the sequence No injuries were reported by any of the drivers or passengers at the scene We documented the scene by taking several photographs of the vehicles and their positions.	PIE towards Tuas near Adam Road. Suddenly, the vehicle in front of me came to an abrupt stop. I managed to stop my vehicle in time to avoid colliding with the vehicle ahead. Shortly after stopping, I felt an impact from the rear of my vehicle, followed by a second impact. These two impacts pushed my vehicle forward, causing it to collide with the vehicle in front of me. Unfortunately, I did not get the licence plate number of the vehicle in front. - I exited my vehicle to assess the situation. - The driver of the vehicle in front, which my vehicle collided with, also exited and inspected his car. - The driver of the front vehicle indicated that the damage to his car was not serious and decided to leave the scene without further action. - I observed that Vehicle B (SNH520H) had collided with the rear of my vehicle, and Vehicle C (YQ1373G) was the last vehicle in the sequence. - No injuries were reported by any of the drivers or passengers at the scene. - We documented the scene by taking several photographs of the vehicles and their positions. - After documenting the scene, all parties left the area.		
These two impacts pushed my vehicle forward, causing it to collide with the vehicle in front of me. Unfortunately, I did not get the licence plate number of the vehicle in front. - I exited my vehicle to assess the situation. - The driver of the vehicle in front, which my vehicle collided with, also exited and inspected his car. - The driver of the front vehicle indicated that the damage to his car was not serious and decided to leave the scene without further action. - I observed that Vehicle B (SNH520H) had collided with the rear of my vehicle, and Vehicle C (YQ1373G) was the last vehicle in the sequence. - No injuries were reported by any of the drivers or passengers at the scene. - We documented the scene by taking several photographs of the vehicles and their positions.	These two impacts pushed my vehicle forward, causing it to collide with the vehicle in front of me. Unfortunately, I did not get the licence plate number of the vehicle in front. - I exited my vehicle to assess the situation. - The driver of the vehicle in front, which my vehicle collided with, also exited and inspected his car. - The driver of the front vehicle indicated that the damage to his car was not serious and decided to leave the scene without further action. - I observed that Vehicle B (SNH520H) had collided with the rear of my vehicle, and Vehicle C (YQ1373G) was the last vehicle in the sequence. - No injuries were reported by any of the drivers or passengers at the scene. - We documented the scene by taking several photographs of the vehicles and their positions. - After documenting the scene, all parties left the area.	PIE towards Tuas near Adam Road, Sudden	ly, the vehicle in front of me came to an abrupt
 The driver of the vehicle in front, which my vehicle collided with, also exited and inspected his car. The driver of the front vehicle indicated that the damage to his car was not serious and decided to leave the scene without further action. I observed that Vehicle B (SNH520H) had collided with the rear of my vehicle, and Vehicle C (YQ1373G) was the last vehicle in the sequence. No injuries were reported by any of the drivers or passengers at the scene. We documented the scene by taking several photographs of the vehicles and their positions. 	- The driver of the vehicle in front, which my vehicle collided with, also exited and inspected his car. - The driver of the front vehicle indicated that the damage to his car was not serious and decided to leave the scene without further action. - I observed that Vehicle B (SNH520H) had collided with the rear of my vehicle, and Vehicle C (YQ1373G) was the last vehicle in the sequence. - No injuries were reported by any of the drivers or passengers at the scene. - We documented the scene by taking several photographs of the vehicles and their positions. - After documenting the scene, all parties left the area.	These two impacts pushed my vehicle forward	rd, causing it to collide with the vehicle in front of
 The driver of the vehicle in front, which my vehicle collided with, also exited and inspected his car. The driver of the front vehicle indicated that the damage to his car was not serious and decided to leave the scene without further action. I observed that Vehicle B (SNH520H) had collided with the rear of my vehicle, and Vehicle C (YQ1373G) was the last vehicle in the sequence. No injuries were reported by any of the drivers or passengers at the scene. We documented the scene by taking several photographs of the vehicles and their positions. 	- The driver of the vehicle in front, which my vehicle collided with, also exited and inspected his car. - The driver of the front vehicle indicated that the damage to his car was not serious and decided to leave the scene without further action. - I observed that Vehicle B (SNH520H) had collided with the rear of my vehicle, and Vehicle C (YQ1373G) was the last vehicle in the sequence. - No injuries were reported by any of the drivers or passengers at the scene. - We documented the scene by taking several photographs of the vehicles and their positions. - After documenting the scene, all parties left the area.	- Levited my vahicle to assess the situation	
decided to leave the scene without further action. - I observed that Vehicle B (SNH520H) had collided with the rear of my vehicle, and Vehicle C (YQ1373G) was the last vehicle in the sequence. - No injuries were reported by any of the drivers or passengers at the scene. - We documented the scene by taking several photographs of the vehicles and their positions.	decided to leave the scene without further action. - I observed that Vehicle B (SNH520H) had collided with the rear of my vehicle, and Vehicle C (YQ1373G) was the last vehicle in the sequence. - No injuries were reported by any of the drivers or passengers at the scene. - We documented the scene by taking several photographs of the vehicles and their positions. - After documenting the scene, all parties left the area.	- The driver of the vehicle in front, which my	vehicle collided with, also exited and inspected his
 (YQ1373G) was the last vehicle in the sequence. No injuries were reported by any of the drivers or passengers at the scene. We documented the scene by taking several photographs of the vehicles and their positions. 	(YQ1373G) was the last vehicle in the sequence. No injuries were reported by any of the drivers or passengers at the scene. We documented the scene by taking several photographs of the vehicles and their positions. After documenting the scene, all parties left the area.		
- We documented the scene by taking several photographs of the vehicles and their positions.	- We documented the scene by taking several photographs of the vehicles and their positions. - After documenting the scene, all parties left the area. - After documenting the scene, all parties left the area. - After documenting the scene, all parties left the area.		
- After documenting the scene, all parties left the area.	aration	- No injuries were reported by any of the drive	ers or passengers at the scene.
		- After documenting the scene, all parties left	the area.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Timé

Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver.
- Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Traffic Police Department for investigation.

- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.


8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

h -		Power
Policyholder's Signature / Date & Time	Oriver's Signature (if driver is not the policyholder) / Date & Time	Witnessed by Reporting Centre Personnel (Name as in NRIC/ID card)
	OC FITTING	(wante as in Which braid)

Sketch Plan



Accident report SW0E246F0003

















Contact us at

Hotline: (65) 6665 5555

E-mail: customerservice@directasia.com

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) (Singapore) (the "Act") Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960 (Singapore) Road Transport Act, 1987 (Malaysia)

Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

This document forms part of your contract with us and should be read together with your Policy Schedule and your Policy Details. Do let us know if any of the details shown here need to be amended or updated.

Certificate No.

: MT/00866722/03

Type of Coverage / Driver Plan

: Car Comprehensive (Value Plus Plan)

1) Vehicle Registration No.

: S1U3296P

Chassis No.

: KNAFW411MA5113856

2) Name of Policy Holder

BTE TUGIRAN S ROSNAHNI

3) Effective Date / Time of Commencement of Insurance for the Purpose of the Act

: 30/11/2023 00:00

4) Date/Time of Expiry of Insurance

29/11/2024 23:59

5) Persons or Classes of Persons Entitled to Drive

- (a) Any named person under the policy who is driving on the Policyholder's permission.
- (b) Any authorised person, provided such person is aged 30 and above and holds a valid driving licence of 2 years or more, who is driving on the Policyholder's permission

The person driving must have a valid driving licence to drive in Singapore and must not be under suspension or disqualification from driving.

6) Limitations as to use*

Use only for private purposes, in accordance with the declared car usage stated on your Policy Schedule. The policy does not cover use for hire or reward, tuition, driving test, racing, pace-making, reliability trials, speed tests, the carriage of goods for payment or for any purpose in connection with the motor trade business. Grab Hitch will only be covered if this is the declared usage stated on your Policy Schedule.

*Limitations rendered inoperative by Section 8 of the Act and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under this heading.

Sum Insured

Market Value

Own Damage Excess

: S\$ 600.00

Windscreen Excess

S\$ 100.00

Choice of workshop

: DirectAsia approved workshops

Finance company / Hire Purchase

.

Main driver

BTE TUGIRAN S ROSNAHNI

Named driver

: None

Important Note: This policy does not cover the Policyholder/drivers below the age of 30 and Policyholder/drivers who hold a valid driving licence of less than 2 years with the exception of the main/named drivers above.

I/We hereby certify that the Policy to which this Certificate relates to is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and the Road Transport Act, 1987 (Malaysia).

Issued on:

13/10/2023

Direct Asia Insurance (Singapore) Pte. Ltd.

Underwriting Manager

Direct Asia Insurance (Singapore) Pte Ltd 20 Anson Road #08-01 Twenty Anson Singapore 079912 www.DirectAsia.com

N-CI