

COMFORTDELGRO ENGINEERING

Sheet1

ComfortDelGro Engineering Pte Ltd
205 Braddell Road Singapore 579701

Mainline +65 6383 6280
Facsimile +65 6280 9755

www.cdge.com.sg

Company Registration No: 198608048W

Workshops

Braddell
205 Braddell Road
Singapore 579701

Loyang
59 Loyang Drive
Singapore 508969

Sin Ming
383 Sin Ming Drive
Singapore 575717

Pandan
45 Pandan Road
Singapore 609288

Ubi
320 Ubi Road 3
Singapore 408649

Senoko
24 Senoko Loop
Singapore 758156

Sungei Kadut
7 Sungei Kadut Way
Singapore 728791

Defu
6 Defu Avenue 1
Singapore 530587

Marymount
600 Sin Ming Avenue
Singapore 575733

Our Ref: 305605914V

Date: 04.10.24

Time of Fax:

Lompac

Via Fax: EMAIL

Your Insured: GBK 9634E

Date of Acc: 03.10.24

Attn: Motor Claims Dept.

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO SH 7765M

- 1 The client has engaged us to repair the vehicle and submit claims against the other party/parties involved in the accident.
- 2 In accordance to the motor claims framework, we hereby request your presence At 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.
- 3 Enclosed, please find :
 - I) Our initial estimate of repairs of the damaged vehicle.
 - II) Accident report made by our client.
- 4 I would appreciate it if you could call us to arrange for the survey of the vehicle

Lim Tien Siong	Tel no. 62148355 or Hp no. 96355341
Jumari Masudin	Tel no. 62148315 or Hp no. 96355305
Chiang Liat Choon	Tel no. 62148314
Lim Tien Siong	Tel no. 62148398 or Hp no. 96355846

- 5 If we do not hear from you within the next 48 hours, we shall deem it that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for loss of use and loss of rental during any delayed period of this survey arrangement.
- 6 This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the insurance company.
- 7 Thank you.

Yours faithfully


for Vice President
Crash Repairs & Claims Recovery

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SH7765M

DATE

04.10.2024

MAKE 05.07.2017

MODEL PRIUS G4

CHIANG/ LONPAC

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR FENDER LH			\$992.04
1	REAR VIEW MIRROR COVER LH			\$108.00
1	REAR VIEW MIRROR ASSY LH			\$1,986.90
1	REAR DOOR PANEL LH			\$1,258.30
1	ROCKER PANEL GARNISH LH			\$576.00
1	REAR WHEEL RIM ALU.			\$1,570.55
	SUB TOTAL			\$6,491.79
	LESS 25%			\$1,622.94
	DISCOUNTED TOTAL			\$4,868.84
1	PETROL STICKER LH			\$25.00
1	REAR DOOR COMFORT APP LH			\$80.00
1	FRONT DOOR PANEL COMFORT STICKER LH			\$75.00
				\$180.00
	Labour Charge			
	Panel Beating			\$1,200.00
	Spray Painting Charge			\$1,200.00
	Trafer Door Parts			\$90.00
	Remove/Refix Upholstery			\$90.00
	TOTAL LABOUR			\$2,580.00
	ESTIMATE TOTAL			\$7,448.84
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			