



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24060201/Kvh3e2
(BUDGET DIRECT INSURANCE)	Date:	24/06/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFB 777K	Veh. Inspected	SNE 7119D
Policy No.	P11059869R00	Coverage	0
Claim No.	C10030084/ML	Excess	\$0.00
Assign From	MICHAEL	Assign Date	24/06/2024

2. Vehicle Details

Make & Model	HYUNDAI KONA (A)	C.C	1580
Engine No.	G4LENU209819	Year of Reg.	01/04/2022
Chassis No.	KMHK281EVNU089167	Colour	WHITE
Odometer	98540 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/60R16	KAPSEN	5
L/H Front Tyre	205/60R16	KAPSEN	5
R/H Rear Tyre	205/60R16	KAPSEN	3
L/H Rear Tyre	205/60R16	KAPSEN	3

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	20/06/2024	Inspection Date	25/06/2024
Survey held at	THIAM HENG HUAT PTE LTD 176 SIN MING DRIVE #05-14 SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days