REF: CS/CTI24100117/Aqh3

ASSIGNMENT

From: Date:

Estimate Amount:

OD / TP / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at WO Workshop/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SNA5576B Yr Regn: 2020, March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Hyundai i30 c.c 1353

Colour Black A/C: Insured / Std / NI / NA

Sp.Reading 64333 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: TMAH3513VLJ119040

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/40R18

R: 225/40R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	08/10/24

Survey held at Modern

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP China.
	LS $3850, 4 days (Red $8357.76, 68%)
	MV : 841C
	PV : 31.5K
	Nett : 52.51C
	631C

COE Expiry :

Estimate given during 1st Survey : Yes ( ) No (✓)

Date/Time, File Pass to? 1) 05/02 Typist

☐ : Preli. Report

☐ : Final Report

Date/Time, File Return to? 2)

Days Of Repair: 4

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Inve ($)

Survey Fee:

Transportation: S + RS. $

Photos

Others

Report Format : EZCLAIMS-TP