

ASSIGNMENT

Front: _____ Date: _____

Estimate: _____

OD / TP RES / CD RES / EVA / INV / MV

To In Vehicle No: _____

at WO / TP / CD / EVA / INV / MV

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle: _____

(Policy Condition)

Remark: Vehicle had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLM9867X Yr Regn: 2017 / April

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Mazda 3 C.D. 1496

Colour: Bronze A/C: Insured / Std / NI / NA

Sp. Reading: 444435 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BN22A8H0150185

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 205/55R16

BS / DUN / EXNQA / GY / FS / IZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Arivo

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. _____ D.O.I. 08/10/24

Survey held at A-Tec

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AWA

COE Expiry:

Estimate given during: Yes (✓)

1st Survey: No ()

MV: 35K

PV: 18.4K

Nett: 16.6K

7.68M

Date/Time, File Pass to?

☐ : Preli. Report

1) Date/Time, File Return to?

☐ : Final Report

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

3 + P.S. \$1

Photos

Others

Add Fee: ☐ : Site Insp (\$

☐ : Interview (\$

☐ : Tech. Inve (\$

Report Format: _____

Report Form: _____