

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CD/111/24100135/Uug3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: FBU 1268D

at Workshop m/s B/H/H

of

Insured: PD 82882

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 81512

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 2 days

Res.: Yes or No

Lum Sum: 1.81 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C 623m

Vehicle: IN / OUT

Date: _____

Person Contacted: LIA 8578

Date / Time Action / Instruction 10/3/25 P/P \$ 519.50 : Inform Raymond

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$ _____)

☐

: Preli. Report

☐

: Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

: Site Insp (\$ _____)

☐

: Interview (\$ _____)

☐

: Tech. Invs (\$ _____)

☐

: Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS SI

Photos

Others

TOTAL

Veh No: FBU 1268D Yr Regn: 19/108/22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

AKA OAK

Make: R.A.P. 10NA

c.c Electric

Colour: Green / Blue

A/C: Insured / Std / NI / NA

Sp. Reading: 4851

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: SA1HD SHC.0NC 000056

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 110-90-12 Presq

R: 130-60-13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

CS7

Front

Rear

R/Bal. 7 mm

R/Bal. 7/7 mm

L/Bal. mm

L/Bal. mm

D.O.A. 20/09/24

D.O.I. 7/10/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.



BAN HOCK HIN
Co., Pte Ltd

Fadhli
Co.Reg.No: 197000288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

NO. : 47890

Customer :

INDIA INTERNATIONAL INSURANCE P.L.

64 CECIL STREET

#04-00 & #06-00

IOB BUILDING

SINGAPORE 049711

ATTN: INDIA INTERNATIONAL INSURANCE P.L.

DATE : 05/10/2024

CLAIM NO. : 12616

POLICY NO. : 2024-V5018204-VMF

FROM : RAYMOND

VEHICLE NO. : FBU1268D

MAKE/MODEL : RAP / IONA AKA OAK

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	4.00	\$85.00	340.00
2	MUDGUARD FRONT P/N: 77062 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$99.00	99.00
3	RIM FRONT ASSY P/N: 81954 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$392.00	392.00 X
4	SENSOR WHEEL SPEED P/N: 83792 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$124.00	124.00
5	SIGNAL FRONT LH ASSY P/N: 81980 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$132.00	132.00
6	STEERING CONE SET P/N: 81975 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$164.00	164.00 X
7	TRANSPORT CHARGES (MOTORCYCLE) OVERSIZED P/N: 45837 - BIKE TOWED BACK TO BHH		1.00	\$108.00	108.00 X

SUB TOTAL

\$1,359.00

GST @ 9 %

\$122.31

GRAND TOTAL (SGD)

\$1,481.31

50% deposit required before ordering of parts.

Validity: 30 days

*47890 *

UKK Auto Consultants hence notify
the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged parts, to be resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledge by Repairer

Signature:

Date:



DATA PROTECTION
ASSURED

bizSAFE₃



Blk 8 Defu South Street 1, #04-28, JTC Defu Industrial City, Singapore 533758 | Tel: +65 6281 6520 | www.bhh.com.sg
Fax: (Main) + 65 6281 2830, (Spare Parts) + 65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) + 65 6281 6759

CERT NO.: 2802-1-0383
ISO 9001: 2015

<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
------------	--------------------	---------------	------------	-------------------	---------------

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

*47890 *

DATA PROTECTION
ASSUREDbizSAFE₃

Blk 8 Defu South Street 1, #04-28, JTC Defu Industrial City, Singapore 533758 | Tel: +65 6281 6520 | www.bhh.com.sg
Fax: (Main) + 65 6281 2830, (Spare Parts) + 65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) + 65 6281 6759

CERT NO.: 2002-1-0363
ISO 9001: 2015