COMEODIDELCDO

COMPORTUELGRO			
ENGINEERING			
ComfortDelGro Engineering Pte Ltd			
59 Loyang Drive Singapore 508969			
Fax: 6546 8156			

Our Job Ref No Date			ENGIN	ENGINEERING			
		10.10.2024		IGro Engineering Pte Ltd			
FINA	ALIZATI	ON FORM	Fax: 6546	Drive Singapore 50896 3156			
To :LKK			Fax:				
Attn	iii y	TAUFIKH					
Vehi	icle Reg	No. : SHA4588U	Date of Accident :	04.10.2024			
The	survey a	and estimates of the repairs of the abo	ove-mentioned vehicle are as foll	ows:-			
1.	The re	epair job shall bill to: TO	KIO MARINE	SLJ3268E			
2.	The fir	nalized amount shall be:					
	(a)						
	(b)	Labour Charges (include advertiser	ment stickers etc,if any)				
	(c.)	Lumpsum Repair (if applicable)					
		Total for Lumpsum repair cost after L	_ess: 20%	\$2,100.00			
		Final Lumpsum Repair cost		\$2,100.00			
3.	Estima	ated normal period for repairs:	2 working days.				
		-					
4.		all treat the above amount as Corre 7 working days	ect and Confirmed if there is n	o reply from you			
5.	Thank	you for your assistance.	We confirm the estir finalized amount	We confirm the estimates and finalized amount			
	Signati	ure:	Signature :				
	Name	LIMTS	Name :	TAUFIKH			
	Tel	62148398	Date :				
	Fax	: 65468156					
		Jse Only					

## Fo

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
Rental Rate P/Day		YES		
2. Loss of Income Paid	3.777	N		
3. Survey Fees	Section	- 122		
4. LTA Search Fee / GEARS	\$27.25 / \$2.18	Υ		
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks	:			
	-			