



Your Ref: 23/24/24/VP96/416955

Date: 09th Oct 2024

Our Ref: CS1/LPM24100144/Enh3e2

M/s Lonpac Insurance Bhd

21st Flr, Bangunan Public Bank

No. 6 Jalan Sultan Sulaiman

50000 Kuala Lumpur, Malaysia

(The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMJ 1034P

INSURED VEHICLE: BPJ 3883

ACCIDENT DATE: 22/05/2024

We thank you for your instruction on 04/10/2024.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMJ 1034P from M/s WG Appraisal Services.
- b) Final Repair Bill of SMJ 1034P from M/s S Three Automotive & Recovery Pte Ltd.
- c) Singapore Accident Statement and Police Report of Vehicles SMJ 1034P.
- d) Polis Diraja Malaysia of Vehicles SMJ 1034P and BPJ 3883
- e) Colour damaged vehicle photographs of SMJ 1034P.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: SMJ 1034P
Make & Model	: KIA Cerato 1.6(A) EX
Year of Registration	: 2019
Chassis Number	: KNAF3416MK5030019
Engine Capacity	: 1591 cc

- 2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.