

REF: CS1/LPM24100144/Enh3 (SMJ 1034P)

Special Instruction:

ASSIGNMENT (Office)

From (Person): Ko Siew Ling of LPM Date/Time: 04/10/2024

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

L/SUM : \$ 7,100 / REPAIR : 5 WORKING DAYS

Third Parties:

Claimant:

Surveyor: WG APPRAISAL SERVICES

Workshop: S THREE AUTOMOTIVE &  
RECOVERY PTE LTD

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SMJ 1034P Insured: BPJ 3883

at Workshop m/s S THREE AUTOMOTIVE & RECOVERY PTE LTD Tel:

of BLK 8 SIN MING IND EST #01-64/66 SINGAPORE 575643

Policy No: \_\_\_\_\_ Claim No: 23/24/24/VP96/416955

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 22/05/2024  
(Client's Record)

(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle IN / OUT \_\_\_\_\_

Date/Time: 08/10/24 Confirmed with \_\_\_\_\_ Final Fig \_\_\_\_\_, \_\_\_\_ days (Red \$\_\_\_\_/\_\_\_\_%; Original \_\_\_\_ days)

Date/Time: 08/10/24 Submit Final Fig 1800, 4 days (Red \$ 5300 / 74 %; Original 5 days)

[illegible]

**Para(1) : Parts found not replaced (To highlight *R* or *UB*, *LR*, *Etc*)**

**Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)**

**Para(3) : Nett Value**

Market Value : \_\_\_\_\_

Salvage Value : \_\_\_\_\_

Nett Value : \_\_\_\_\_

Inspected/  
Evaluated by:

*Fee Charged:*

Basic &amp; Add

Transport

## Photos

Others

Total

Date: \_\_\_\_\_

1) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

2) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_

3) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

4) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_

5) Date/Time \_\_\_\_\_ File Pass to \_\_\_\_\_

6) Date/Time \_\_\_\_\_ File Return to \_\_\_\_\_