

(06/11/13) Wef
ASS. REC. BY:

REF: CS/FCI 24100156/Rvp3

3772

ASSIGNMENT

2026/004

From: _____ Date: _____
Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
To Inspect Vehicle No: SGK 6259R
at Workshop m/s SHU FATT
of BUKIT MERAH
Insured: SH 8566P FCI 2
Policy No. _____
Claims No. D24008732MFCT
Sum Insured: _____ Excess: _____
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 16K
IDAC Accident Report: Consistent?: Yes or No
GIA / PR Seen: Consistent?: Yes or No
Est. Repairs: days Res.: Yes or No
Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGK 6259R Yr Regn: 2006 Msh
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: SUBARU IMPREZA 5m1 c.c. 1597
Colour: BLUE A/C: Insured / Std / Nil / NA
Sp. Reading: 185913 T/Radio: Insured / Std / Nil / NA
Eng/No: _____
C/No: JF1605KJ366057171
Gen. Cond: Good / Fair / Poor / Burnt
Steering: Inorder / Jammed / Leaked / Burnt or
Brake: Inorder / Jammed / Leaked / Burnt or
Modi: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 225/45ZR17
R: 225/45ZR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front Rear
R/Bal. 6 mm R/Bal. 6 mm
L/Bal. 6 mm L/Bal. 6 mm
D.O.A. 02/10/24 D.O.I. 10/10/24
Survey held at BUKIT MERAH

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

O/S Fnt
The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

REPAIR LIMIT - 6K

20/12/24 submit preli report-revised \$2247.12 check items \$92.96

The vehicle has not send in for repair

Date/Time, File Pass to?

☐
☐

: Preli. Report

: Final Report

1) _____
Date/Time, File Return to?

2) _____

Days Of Repair: 3

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others

Add Fee: ☐ : Site Insp (\$ _____)

☐ : Interview (\$ _____)

☐ : Tech. Invs (\$ _____)

☐ : Weekend (\$ _____)

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____



樹發汽車修理廠 SHU FATT AUTO WORKS

BLOCK 1009 BUKIT MERAH LANE 3 #01-90 SINGAPORE 159723 TEL: 6273 0119 FAX: 6270 7065

Co. Reg. No. 09062400M GST Reg. No. M 90375389 A

Our Ref: WSK/jw/SF-quo
3rd October 2024

MS First Capital Insurance Ltd
(Third Party)

SGK 6259 R SUBARU IMPREZA

		S\$
Spare Parts	1 Rt frt headlight. <i>SEA</i> /	1100.00
	1 Rt frt headlight holder. <i>X</i>	82.10
	1 Rt frt fender cowl. <i>X</i>	96.40
	1 Frt bumper. <i>SEA</i> /	681.00
	1 Frt bumper reinforcement. <i>X</i>	415.20
	1 Rt frt bumper bracket. <i>?</i>	68.00
	1 Frt bumper side retainers. @\$48.20 <i>?</i>	96.40
	1 Rt frt fog light garnish. <i>MIS</i> /	115.40
	1 Set rt frt fender cowl. clips. <i>X</i>	60.00 snet <i>X</i>
	1 Set frt bumper clips. <i>m</i> /	72.00 snet
		<u>30</u> 72.00
		2786.50
Less 20%		530.90
		<u>2255.60</u>
Labour	To knock, straighten frt support panel, frt inner panel, frt lower panel, frt side panel, rt frt fender, renew frt light, frt bumper and assembly.	450.00 <i>300</i>
	To respray damaged parts.	680.00 <i>400</i>
		<u>3385.60</u>

Michelin 225/45ZR17
JF1GD5KJ36G057177
185668

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Ran
Hp 90010068
3 deep
45
10/10/24
Reg after repair

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	377I
Vehicle Details	
Vehicle No.:	SGK6259R
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Oct 2024
Vehicle Make:	SUBARU
Vehicle Model:	IMPREZA 5MT
Primary Colour:	Blue
Manufacturing Year:	2006
Engine No.:	EJ16C841166
Chassis No.:	JF1GD5KJ36G057177
Maximum Power Output:	70.0 kW (93 bhp)
Open Market Value:	\$12,277.00
Original Registration Date:	21 Aug 2006
First Registration Date:	21 Aug 2006
Transfer Count:	1
Actual ARF Paid:	\$10,072.00
Intended PARF Rebate Details	
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Aug 2026
COE Category:	E - Open Category
COE Period(Years):	10
PQP Paid:	\$51,518.00
COE Rebate Amount:	\$9,569.00
Total Rebate Amount:	\$9,569.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 11 Oct 2024

OK