

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: FBS 8440L Yr Regn: 2021, 08
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: Yamaha Sniper 155 c.c. 155
 Colour: Gold A/C: Insured / Std / NI / NA
 Sp. Reading: - T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: RLKUG1610MY001005
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Inorder / Jammed / Leaked / Burnt or _____
 Brake: Inorder / Jammed / Leaked / Burnt or _____
 Mod: NW / S/Rim / STD A/Rim or _____
 Tyre Size: F: 90/90R17
 R: 70/90R17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

(Policy Condition)
 Remark: The veh had commenced its
 repair at the time of inspection.

<u>WIP</u>	
N/S	O/S

Bal. or Market Value: \$14K
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lump Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS PRY WP
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Front 5 Rear _____
 R/Bal. _____ mm R/Bal. 5 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. _____ D.O.I. 19/6/24 0415pm
 Survey held at Gusto Bros
 Des. of Damages FR / Rear / OS / N/S / U/G / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair Range: \$5000 - \$6000 6 days</u>

Date/Time, File Pass to? : Prel. Report
 : Final Report
 i) _____
 Date/Time, File Return to?

Days Of Repair: _____
 Resurvey No. of Trip: _____

2) _____
 Rep. Format: _____
 Lump Sum / I.B.I. (%): _____

Add Fee: : Site Insp (\$))
 : Interview (\$))
 : Tech. Invs (\$))
 : Weekend (\$))

Survey Fee: _____
 Transportation: _____ \$ + RS _____ \$
 Photos _____
 Others _____
 TOTAL _____