



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

STRIDES PREMIER AUTOMOTIVE SERVICES PL.
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

INV No. : SAC2400077

INV Date : 17-07-2024

Reference CS3/SMR24060207/Ence2

Code SMR

PROFESSIONAL SERVICE FEE

Vehicle No. SNE 4242A
Insured Veh. SHD 6273Z
Claim No. TAX/06/24/2031
Policy No.
Accident Date 11/06/2024
Inspection Date 14/06/2024

Description	Amount
Pre-Repair Survey	128.00
Sub-Total	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS STRIDES PREMIER AUTOMOTIVE SERVICES PL.		Ref:	CS3/SMR24060207/Ence2	
60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE		Date:	17/07/2024	
757705		Code:	SMR	
1. Policy Particulars :- PRE-REPAIR SURVEY				
Insured Veh.	SHD 6273Z	Veh. Inspected	SNE 4242A	
Policy No.	-	Coverage	0	
Claim No.	TAX/06/24/2031	Excess	\$0.00	
Assign From	-	Assign Date	14/06/2024	
2. Vehicle Details				
Make & Model	HONDA ACCORD EURO R	C.C	1998	
Engine No.	K20A6540642	Year of Reg.	02/04/2007	
Chassis No.	CL71300600	Colour	BLUE	
Odometer	280575 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	FAIR	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	235/40Z R18	KUMHO	5	
L/H Front Tyre	235/40Z R18	KUMHO	5	
R/H Rear Tyre	235/40Z R18	KUMHO	5	
L/H Rear Tyre	235/40Z R18	KUMHO	5	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
5. General Information				
Accident Date	11/06/2024	Inspection Date	14/06/2024 (02:08PM)	
Survey held at	TECHNEAT PTE LTD 8 KAKI BUKIT AVENUE 4, #03-38/39 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				

CTY

CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A




PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A




PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A




PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A



PHOTOGRAPHS FOR VEHICLE NO. : SNE 4242A

