

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 09/10/2024

User ID : choonhwee03

Section A - Accident Details			
Registration Number	SMB1306Y		
Case Reference Number	BUS/10/24/5007		
Registration Date	1/29/2013		
Company Type	SMRT Buses Ltd		
Make	MAN		
Model	MAN NL320F(A22)		
Name of Driver	Wang ZhaoYun		
Type of Accident	Side Swipe		
Accident Date and Time	10/3/2024 10:43 AM		
Accident Reported Date and Time	10/4/2024 4:21 PM		
Is Surveyor Required?	No		
Survey by			
Vehicle is Towed Back?	No		
Towed Back Date and Time			
Replacement Vehicle issued?	No		
Job Card Number			
Special Instruction to ARC, if any	Bus damage: Right view mirror dislodged TP: XD8188J - 3P insured with Lonpac Insurance 04.10.2024 (KC) Pend Gears 04.10.2024 (KC)		
Prepared Date and Time	10/7/2024 8:39 AM		
Chassis Number	WMAA222Z0D7001726		
Mileage			
Work Shop			
Repair Completion Date and Time			
Section B - Summary of Repair Estimates			
Summary of Repair Estimates			
	Quotation from ARC	Adjusted by Surveyor, if applicable	
Total Labour Cost	\$265.00	\$0.00	
Total Spray Cost	\$0.00	\$0.00	
Total Spare Part Cost	\$896.33	\$0.00	
Total Other Cost	\$200.00	\$0.00	
TOTAL COST	\$1,361.33	\$0.00	
Lump Sum Total	\$0.00	\$0.00	
Number of Repair Days	1.0		
Prepared / Adjusted By	Kok Khoon Goh		
ARC / Surveyor Sign Off Date	07/10/2024 8:41 AM		
Signature			
Remarks			
Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 09/10/2024

User ID : choonhwee03

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope		Quotation from AR				Adjusted by Surveyor, if applicable			
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.		\$265.00				132.50			
Total Labour		\$265.00							
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
Total Spray Painting & Panel Beating									
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
TOWING CHARGE		\$200.00				1/10/24 / ARC			
Total Other Costs		\$200.00							
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010161	BODY RH	4001M01-ACCE467	MIRROR,VIEW.FRONT,R H,FOR MAN	1.00	\$1,244.90	10.00	\$1,120.41	Replace	HP
Total					\$1,244.90		\$1,120.41		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

STER (LKK)
10/10/24, 11.00am
m R
1 day
M Am y
L/S

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____