

# SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705

FAX Number: 63685592

Estimator Telephone Number: 68662623

Accident Reporting Number: 68662672

Date Generated: 09/10/2024
User ID: choonhwee03

	Section A - Accident	Details
Registration Number	SMB1306Y	
Case Reference Number	BUS/10/24/5007	
Registration Date	1/29/2013	
Company Type	SMRT Buses Ltd	
Make	MAN	
Model	MAN NL320F(A22)	The second secon
Name of Driver	Wang ZhaoYun	
Type of Accident	Side Swipe	The second secon
Accident Date and Time	10/3/2024 10:43 AM	
Accident Reported Date and Time	10/4/2024 4:21 PM	The second printer in the second seco
Is Surveyor Required?	No	
Survey by		
Vehicle is Towed Back?	No	Committee of the second
Towed Back Date and Time		
Replacement Vehicle issued?	No	
Job Card Number		
Special Instruction to ARC,if any	Bus damage: Right view mirror d TP: XD8188J - 3P insured with L Pend Gears 04.10.2024 (KC)	islodged onpac Insurance 04.10.2024 (KC)
Prepared Date and Time	10/7/2024 8:39 AM	
Chassis Number	WMAA22ZZ0D7001726	
Mileage		Corresponding to the comment of the
Work Shop		
Penair Completion Date and Time		Control of the Contro
Repair Completion Date and Time	Costina B. Summanı of Ro	nair Fetimates
	Section B - Summary of Re	pair Estimates
	Section B - Summary of Re	Pair Estimates  Adjusted by Surveyor, if applicable
Summary of Repair Estimates		Adjusted by Surveyor, if applicable
Summary of Repair Estimates  Total Labour Cost	Quotation from ARC	Adjusted by Surveyor, if applicable
Summary of Repair Estimates  Total Labour Cost  Total Spray Cost	Quotation from ARC \$265.00	Adjusted by Surveyor, if applicable
Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spare Part Cost	Quotation from ARC \$265.00 \$0.00	Adjusted by Surveyor, if applicable \$0.00 \$0.00
Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spare Part Cost  Total Other Cost	Quotation from ARC \$265.00 \$0.00 \$896.33 \$200.00	Adjusted by Surveyor, if applicable \$0.00 \$0.00 \$0.00
Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spare Part Cost  Total Other Cost	Quotation from ARC \$265.00 \$0.00 \$896.33	Adjusted by Surveyor, if applicable \$0.00 \$0.00 \$0.00 \$0.00
Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spare Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total	Quotation from ARC \$265.00 \$0.00 \$896.33 \$200.00 \$1,361.33	Adjusted by Surveyor, if applicable \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00
Summary of Repair Estimates  Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days	Quotation from ARC \$265.00 \$0.00 \$896.33 \$200.00 \$1,361.33 \$0.00	Adjusted by Surveyor, if applicable \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00
Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Spare Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days  Prepared / Adjusted By	Quotation from ARC \$265.00 \$0.00 \$896.33 \$200.00 \$1,361.33 \$0.00 1.0 Kok Khoon Goh	Adjusted by Surveyor, if applicable \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00
Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Sprae Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days  Prepared / Adjusted By  ARC / Surveyor Sign Off Date	Quotation from ARC \$265.00 \$0.00 \$896.33 \$200.00 \$1,361.33 \$0.00	Adjusted by Surveyor, if applicable \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00
Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Sprae Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days  Prepared / Adjusted By	Quotation from ARC \$265.00 \$0.00 \$896.33 \$200.00 \$1,361.33 \$0.00 1.0 Kok Khoon Goh	Adjusted by Surveyor, if applicable \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00
Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date	Quotation from ARC \$265.00 \$0.00 \$896.33 \$200.00 \$1,361.33 \$0.00 1.0 Kok Khoon Goh	Adjusted by Surveyor, if applicable \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00
Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Sprare Part Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days  Prepared / Adjusted By  ARC / Surveyor Sign Off Date  Signature	Quotation from ARC \$265.00 \$0.00 \$896.33 \$200.00 \$1,361.33 \$0.00 1.0 Kok Khoon Goh	Adjusted by Surveyor, if applicable \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00
Summary of Repair Estimates  Total Labour Cost Total Spray Cost Total Sprae Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date Signature  Remarks	Quotation from ARC \$265.00 \$0.00 \$896.33 \$200.00 \$1,361.33 \$0.00 1.0 Kok Khoon Goh	Adjusted by Surveyor, if applicable \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00
Summary of Repair Estimates  Total Labour Cost Total Spray Cost Total Spare Part Cost Total Other Cost TOTAL COST Lump Sum Total Number of Repair Days Prepared / Adjusted By ARC / Surveyor Sign Off Date Signature  Remarks	Quotation from ARC \$265.00 \$0.00 \$896.33 \$200.00 \$1,361.33 \$0.00 1.0 Kok Khoon Goh 07/10/2024 8:41 AM	Adjusted by Surveyor, if applicable \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00  \$0.00
Summary of Repair Estimates  Total Labour Cost  Total Spray Cost  Total Other Cost  TOTAL COST  Lump Sum Total  Number of Repair Days  Prepared / Adjusted By  ARC / Surveyor Sign Off Date  Signature  Remarks	Quotation from ARC \$265.00 \$0.00 \$896.33 \$200.00 \$1,361.33 \$0.00 1.0 Kok Khoon Goh 07/10/2024 8:41 AM	Adjusted by Surveyor, if applicable \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00  \$0.00  \$under the state of the state

Page 1 of 2



#### **SMRT Accident Vehicle Repair Estimates**

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number: 63685592

Estimator Telephone Number: 68662623

Accident Reporting Number: 68662672

Date Generated : 09/10/2024
User ID : choonhwee03

	Salar Service	THE PARTY OF THE P	Section	on D - Deta	ils of Repair E	stimates		THE RESERVE OF THE PARTY OF	
Part 1 - Labou	r Works		ALLEGER						
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.			\$265.00				132.50		
Total Labour			\$265.00						
Part 2 - Spray	Painting & Pa	anel Beating Rela	ted Works				ES ESTAN		
lob Scope			Quotation from ARC				Adjusted by Surveyo	or, if applicable	
Total Spray Pa	nting & Panel	Beating							
Part 3 - Other	Costs - Accid	lent and Accident	Repair Related Expens	e					
Job Scope		Quotation from ARC				Adjusted by Surveyor, if applicable			
TOWING CHARGE			\$200.00 /hWe				M		
Total Other Costs			\$200.00						
Part 4 - Spare	Parts / Mater	ial Usage		(Zalake I			Barren.	RECYTE DIFFE	
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (S)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010161	BODY RH	4001M01- ACCE467	MIRROR, VIEW: FRONT, R H. FOR MAN	1.00	\$1,244.90	10.00	\$1,120.41	Replace /	111
Total				900	\$1,244.90		\$1,120.41		The Control of the Co
Added Spare	Parts / Materi	al Usage After Su	rveyor Signed off	190		THE REAL PROPERTY.			
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total				-					

SPER (LKK)
10/10/14, 11.0000

M M

1 day

M An 4

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- . To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer Signature:

Date:

Page 2 of 2

SS4B24A4000E / Strides Premier Automotive Services Pte Ltd (486443) ENTRY DATE & TIME: 04/10/2024 16:45 (SGT) SUBMITTED BY: KAREN CHAN SIAU CHIN (SMRT11) VERSION: 1 (04/10/2024 16:45 (SGT))



# SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report <u>correctly</u> the details of the accident to speed up the claims process.

2. This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of First Submission Reported by **Date of Accident Exact Location of Accident** Additional Location Information Country/State of Loss

04/10/2024 16:45 (SGT) Both Policyholder and Actual Driver 03/10/2024 10:43 (SGT) Tampines, Singapore TPE towards SLE before exit 13. Singapore

#### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

**SMB1306Y** 

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Company Reg No

**Email Address** Mobile Phone No Alternative Phone No **SMRT BUSES LTD** 1XXXXX292D

Auto-Svcs-BARC@smrt.com.sg (Phone) +65-68662672

#### VEHICLE PARTICULARS

Manufacturer Model Variant Exact purpose for which vehicle was being used at time of accident Are you claiming under your own insurance policy for repair to your vehicle? Vehicle Category Transmission CC Vehicle Fuel

First Regisration Date Chassis no Effective Date/Time of Ownership **Employment** 

MAN NL320F(A22)

Man

No - Claiming third party Bus

Auto 10815

INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number MS First Capital Insurance Ltd D-24102273MFBP

DRIVER

Accident report SS4B24A4000E

Page 1 of 8



Wang ZhaoYun Name of Driver GXXXX636L Passport No/FIN Date Of Birth 14/02/1985 Outdoor Occupation 08/04/2014 **Driving Pass Date Driving License Pass Class Driving License Validity** Valid 10 YEARS AND 6 MONTHS Driving experience Male Gender (Phone) +65-68662672 Mobile Number Alt. Phone Number Auto-Svcs-BARC@smrt.com.sg **Email Address** 60 WOODLANDS INDUSTRIAL PARK E4 757705 Address Address complement 757705 Postcode No Is the driver the policyholder? If No, Relationship of the Driver with the Insured **Employee** Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver

#### GENERAL INFORMATION OF THE ACCIDENT

Side Swipe Type of Accident Clear Weather Conditions Road Surface

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s) No soliciting/offering accident claims assistance? Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement

# DETAILS OF POLICE ACTION

Yes Was the accident reported to the police? Traffic Police Police Station Name (Phone) +65-65470000 Police Station Phone No (Fax) +65-65474900 Alt. Police Station Phone No 10 Ubi Avenue 3 Singapore 408865 Police Station Address Was notice of intended Prosecution given? No If yes, against whom?

# CIRCUMSTANCES OF ACCIDENT

REFER TO POLICE REPORT NO: T/20241003/7076 On the above mentioned time, date & place, I had a traffic accident which the lorry trailer behind me tried to overtake my bus and the left rear side of the said trailer hit my bus right side mirror.

# ATTACHMENT(S)

Are accident photos available for attachment? Was there any video captured by Car Camera?

No Yes

Accident report SS4B24A4000E

Page 2 of 8

# DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number XD8188J
Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour -

Vehicle Category Commercial vehicle
Name of Driver UNKNOWN
Contact Number

Address - Address complement -

Postcode Insurance Company Name Nature Of Damage -

Details of property damaged in accident

No. Of Passenger (Including Driver)

# SKETCH PLAN

# IMPORTANT NOTICE

- Please report correctly the details of the accident to speed up the claims process
- SMB13064/867 (OSB)
- 2 This Form must be compreted by the Policyholder and/or the Actual Oriver
- 3 Information provided must be as fruthful and accurate as possible. Any wiful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Traffic Police Department for investigation.
- This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties
- 7 By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid

# 8 Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

(a) My insurer, my workshop and the General insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purposo(s) of

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to

- (a) investigating the accident and/or my claims,
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me.

(iv) administering my claims (including the mailing of correspondence, statements, involces, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect. use, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents

(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.




Policyholder's Signature / Date & Time

1A 4.10. 2024

Driver's Signature (if driver is not the policyholder) / Date

Witnessed by Reporting Cen (Name as in NRICAD card)

Sketch Plan



A : SMB13069

[38160x . 8

1



Describe Circumstance of the Acciden	
Refer to Police Rel	POLT NO T/20241003/7076

Declaration

I/We declare the foregoing particulars are true in every respect



Witnessed by Reporting Centre Personnel (Name as in NRICAD care)





Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000 1 of 3 Report No. T/20241003/7076

Date/Time Report Made: 03/10/2024 17:09			Vide Report No.: F/20241003/0078	Station Diary No.		
Informani	's Particular	5				
Name of Informant: WANG ZHAOYUN			Address: 407 FAJAR ROAD #9-321 SINGAPORE 670407			
ID Type / ID No.: FIN NO / G2423636L			Contact No.: Home/Office:	Mobile: 86722678		
Nationality: CHINESE			Email: ZHAOYUNW985@ICLOUD.COM			
Sex: Age: Date of Birth: Male 39 14/02/1985			Type of Informant: BUS DRIVER			
Race: Chinese			Language: English			
Occupation: Bus driver			Driving Licence Information: Class:	Date of Expiry:		

Type of Accident:	of the Accident Non-Injury Others	Drii	nk Drive:	Date/Time of Accider 03/10/2024 10:43	nt: Type of Location Straight Road
Location:	A responsibility and help community the propriet and the property of		to great you may not not be great the second	A MAN COMMUNICATION OF STORY AND STORY AND STORY OF STORY AND STOR	
TPE (SLE) 13KM					
Weather: Clear	AND AND COMPANY OF PROPERTY PROPERTY COMPANY OF THE CONTRACT CONTRACT COMPANY OF THE CONTRACT CONTR	Road Surfa Dry	ice:	about magazindo en deciminado de como	
Traffic Flow: One Way	destination of the party of the first party and the second of the party and the second of the second	Traffic Con Not Contro			Traffic Volume: Light
		and the same and the same and			Anyone conveyed by

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
water the backetone has been been a	Tilbe	The second secon	The second secon	Green		0
XD8188J	Lorry	ISUZU		Giccii		

Details of Person Involved	
Any Pedestrian Involved: No	
No. of Pedestrians Injured: NIL	Use of Pedestrian Crossing: NA



Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No. 65470000



Report No. T/20241003/7076

CONTINUATION OF REPORT

Driver		die enime	ID No		NIL
Name	Unknown Driver		10 140		
Related Vehicle	NIL		Conta	ct No.	NIL
Hospital/Clinic	NIL		Class Driving Licent Expiry	g ce &	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Disc		NIL	
No. of Days granted Medical Leave (MC) NIL		Degree of Injury NIL			
BUS DRIVER		THE THE	IID No.	-	G2423636L
Name	WANG ZHAOYUN		ID No		S242000C
Related Vehicle	NIL		Contact No.		86722678
Hospital/Clinic	NIL		Class Drivin Licent Expiry	9	Class: NIL Date of Expiry: NIL
Date Treatment	NIL	Date Disc	harge	NIL	
Date freatment	d Medical Leave (MC) NIL	Degree of	Injury	NIL	Part of the second seco

On the above mentioned time, date and place, i had an traffic accident, which the lorry trailer behind me tried to overtake me but the lorry trailer rear left side hit my right side mirror.



Police Station Of Origin: Traffic Police 10 Ubi Avenue 3 SINGAPORE 408865 Tel No: 65470000



T/20241003/7076

3 of 3 Report No. T/20241003/7076

CONTINUATION OF REPORT

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by Singpass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 03/10/2024 17:09
Officer In Charge Of Case: TP / AEIT / MUHAMMAD NOOR BIN ABDUL RAHMAN Contact No.: 65476219	Classification Of Caso:
This report is lodged at Woodlands West NPC Kios	k3

NP168