

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internation	ale Des Experts En	Automobile
LONPAC INSURAN	ICE BHD	Ref:	CS/LPC24100198/Eqh3e2
	NCOURSE SINGAPORE 199555	Date:	13/11/2024
#17-04/07 THE CO		Code:	LPC2
	Policy Particulars :-	THIRD PARTY CLA	IM
Insured Veh.	XD 2388M	Veh. Inspected	SLU 2795Z
Policy No.	-	Coverage	0
Claim No.	23/24/24/VC05/029977	Excess	\$0.00
Assign From	ERIC WOO	Assign Date	10/10/2024
2. Vehicle Details			
Make & Model	MAZDA 3	c.c	1496
Engine No.	P520453078	Year of Reg.	28/11/2017
Chassis No.	JM6BN22A8H0160678	Colour	BLUE
Odometer	176515 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		
3. Conditions of Tyres			
	Size	Make	Balance (mm)
R/H Front Tyre	206/60 R16	ARIVO	5
L/LL Event Time	206/60 R16	ARIVO	5
L/H Front Tyre		7	
R/H Rear Tyre	206/60 R16	ARIVO	5
_			5 5
R/H Rear Tyre L/H Rear Tyre	206/60 R16 206/60 R16 Description	ARIVO ARIVO I of Damages	
R/H Rear Tyre L/H Rear Tyre	206/60 R16 206/60 R16	ARIVO ARIVO I of Damages	
R/H Rear Tyre L/H Rear Tyre	206/60 R16 206/60 R16 Description NED DAMAGES AT THE REAR O/S PC	ARIVO ARIVO I of Damages	
R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN	206/60 R16 206/60 R16 Description NED DAMAGES AT THE REAR O/S PC	ARIVO ARIVO I of Damages	
R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN	206/60 R16 206/60 R16 Description NED DAMAGES AT THE REAR O/S PC	ARIVO ARIVO of Damages ORTION.	
R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN IAGES SEE DETAIL	206/60 R16 206/60 R16 Description NED DAMAGES AT THE REAR O/S PC	ARIVO ARIVO of Damages ORTION. Inspection Date	08/11/2024
R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN IAGES SEE DETAIL Accident Date	206/60 R16 206/60 R16 Description NED DAMAGES AT THE REAR O/S PO LS. General I 03/10/2024 A-TEC AUTOMOTIVE PTE LTD - 8 K SINGAPORE 415875	ARIVO ARIVO of Damages ORTION. Inspection Date	08/11/2024
R/H Rear Tyre L/H Rear Tyre VEHICLE SUSTAIN AGES SEE DETAIL Accident Date Survey held at HE INSPECTION W	206/60 R16 206/60 R16 Description NED DAMAGES AT THE REAR O/S PO LS. General I 03/10/2024 A-TEC AUTOMOTIVE PTE LTD - 8 K SINGAPORE 415875	ARIVO ARIVO ARIVO of Damages ORTION. Information Inspection Date CAKI BUKIT AVENUE narks REJUDICE" BASIS.	08/11/2024 £ 4 #04-20 PREMIER @ KAKI BUKIT
	300 BEACH ROAD #17-04/07 THE CO Insured Veh. Policy No. Claim No. Assign From Make & Model Engine No. Chassis No. Odometer Brakes Modification(s)	Insured Veh. XD 2388M	Date: #17-04/07 THE CONCOURSE SINGAPORE 199555 Code:

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days