

SMRT Accident Vehicle Repair Estimates

Section A - Accident Details					
Registration Number	SMB1305A				
Case Reference Number	BUS/09/24/5077				
Registration Date	24/1/2013				
Company Type	SMRT Buses Ltd				
Make	MAN				
Model	A22				
Name of Driver	Abdul Rahim Bin Maulod				
Type of Accident	Side Swipe				
Accident Date and Time	30/9/2024 5:15 PM				
Accident Reported Date and Time	8/10/2024 9:50 AM				
Is Surveyor Required?	Yes				
Survey by					
Vehicle is Towed Back?	No				
Towed Back Date and Time					
Replacement Vehicle issued?	No				
Job Card Number	AWLJ24100037				
Special Instruction to ARC,if any	SMB1305A - LEFT FRONT BUMPER CRACKED GBL2993L (TP) - 3P insured wit India International Insurance 09.10.2024 (KC) TP INSN NO RESULT. *KAREN PLS UPDATE TP INSURANCE*				
Prepared Date and Time	10/10/2024 2:46 PM				
Chassis Number	WMAA22ZZ3D7001722				
Mileage					
Work Shop					
Repair Completion Date and Time					

	Section B - Summary of Repa	air Estimates			
Summary of Repair Estimates					
	Quotation from ARC	Adjusted by Surveyor, if applicable			
Total Labour Cost	\$1,060.00	\$795.00			
Total Spray Cost	\$786.00	\$616.00			
Total Spare Part Cost	\$2,561.40	\$2,561.40			
Total Other Cost	\$0.00	\$0.00			
TOTAL COST	\$4,407.40	\$3,972.40			
Lump Sum Total	\$0.00	\$3,950.00			
Number of Repair Days	3.0	2.0			
Prepared / Adjusted By	Jeong Choon Hwee	STEVE CHEN (LKK)			
ARC / Surveyor Sign Off Date	10/10/2024 2:51 PM	10/10/2024 7:51 PM			
Signature	5	G1404			
Remarks					

Section C - Quotation and Accident Invoice Details				
Quotation Number		Invoice Number		
Quotation Date		Invoice Date		
Invoice Amount		Prepared Date		

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 25/10/2024

User ID : CatherineLee



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 25/10/2024

User ID : CatherineLee

			Section	on D - Detai	ils of Repair E	stimates			
Part 1 - Labou	ır Works								
Job Scope	Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable	
			\$1,060.00				\$795.00		
DAMAGED AFFECTED AREAS. Total Labour			\$1,060.00				\$795.00		
Part 2 - Spray	Painting & P	anel Beating Rela	ted Works						
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$786.00				\$616.00		
			\$786.00				\$616.00		
Part 3 - Other	Costs - Accid	dent and Accident	Repair Related Expens	se					
Job Scope				Quotation from ARC				Adjusted by Surveyor, if applicable	
Total Other Costs									
Part 4 - Spare	Parts / Mater	ial Usage							
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6009375	VM		RETAINER:MALE & FEMALE,REAR LID,MAN BUS	1.00	\$74.80	10.00	\$67.32	Replace	Replace
6010153	Body	F01001-CW264	COVER,HEADLAMP:FRT ,LH,FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	Replace
6010304	VE		HEADLAMP,LH (MAN BUS)	1.00	\$1,603.60	10.00	\$1,443.24	Replace	Replace
6010306	VE		FLASHER,AUX HEADLAMP,LH (MAN BUS)	1.00	\$904.40	10.00	\$813.96	Replace	Replace
6010073	Body		DOME:FRONT,FOR MAN A22 BUS	1.00	\$2,817.50	100.00	\$0.00	Repair	Repair
Total					\$6,375.00		\$3,201.75		
Added Spare	Parts / Mater	ial Usage After Su	rveyor Signed off						
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check

Total