

ASSIGNMENT

From: _____ Date: _____
 Estn: _____
 OD / TP RES / TP RES / OD RES / EVA / INV / MV
 To in _____ Vehicle No: _____
 at _____
 of _____
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client Record)
 Make of Vehicle: _____

Veh No: SKS8913H Yr Regn: 2015, May
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: BMW 420i Gran Coupe 1997
 Colour: Silver A/C: Insured / Std / NI / NA
 Sp. Reading: 137964 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WBA4A1030GK06189
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Modif: Nil / S/Rim / STD A/Rim or _____
 Tyre Size: F: 225/45R18
 R: 225/45R18

(Policy Condition)
 Remark: Vehicle had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / IZA / MIC / DHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front Rear
 R/Bal. 06 mm R/Bal. 06 mm
 L/Bal. 06 mm L/Bal. 06 mm
 D.O.A. _____ D.O.I. 14/10/24
 Survey held at MG Solution
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____
 The U/C / Chassis frame / Body Structure affected due to collision.

Bal. or Market Value: _____
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Date / Time	Action / Instruction
	<u>TPA1h</u>
	<u>COE Expiry</u>
	<u>Estimate given during 1st Survey</u>
	<u>MV: 34K</u>
	<u>PV: 26.9K</u>
	<u>Nett: 7.1K</u>

Date/Time, File Pass to? : Preli. Report
 1) : Final Report
 Date/Time, File Return to?
 2) _____
 Days Of Repair: _____
 Resurvey No. of Trip: _____
 Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech. Inve (\$)
 Survey Fee: _____
 Transportation: _____
 S + R.S. _____
 Photos _____
 Others _____

CHIA AUTO SERVICES PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6243 1373 Fax: 6243 1376

Reg. No: 20158764H

Email: CA3SERVICES@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT
DATE:	10-10-24
CLAIM TYPE:	T/P CLAIM
TO:	AIG
VEHICLE DETAILS	
VEHICLE NO:	SKS8913H
MAKE & MODEL:	BMW 420I
CHASSIS NO:	
ACCIDENT DETAILS	
DATE:	10 October, 2024
TIME:	0920HRS
THIRD PARTY REQUESTOR:	JACK LI

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dehd</i>	1	\$ 1,955.30	\$ 1,955.30
2	REAR BUMPER SIDE RETAINER <i>new</i>	2	\$ 150.00	\$ 300.00
3	REAR BUMPER CENTRE OUTER GARNISH <i>lt</i>	1	\$ 520.00	\$ 520.00
4	REAR BUMPER SENSOR <i>new</i>	2	\$ 280.00	\$ 560.00
5	REAR BUMPER TOWING COVER <i>new</i>	1	\$ 80.00	\$ 80.00
6	REAR BUMPER CENTRE GARNISH <i>last one</i>	1	\$ 250.00	\$ 250.00
7	REAR BUMPER REINFORCEMENT <i>Dented</i>	1	\$ 850.00	\$ 850.00

TOTAL PRICE \$ 4,515.30

LESS 5% \$ 225.77

SUB TOTAL PRICE \$ 4,289.54

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER CLIPS SET <i>new</i>	1	\$ 20.00	\$ 20.00

TOTAL \$ **20.00**

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 1,000.00	\$ 1,000.00
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 1,000.00	\$ 1,000.00
3	TUFF COAT	1	\$ 200.00	\$ 200.00

4	WIRING CHECK	1	\$ 80.00	\$ 80.00	+
5	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	1	\$ 100.00	\$ 100.00	30

TOTAL \$ 2,380.00

ESTIMATE REPORT

TOTAL PARTS COST	\$	4,309.54
TOTAL LABOUR COST	\$	2,380.00
TOTAL REPAIR COST	\$	6,689.54

APPROVED DETAILS:

SURVEYOR:
CONTACT NO.:
PART BY PART/LUMP SUM
NO. OF DAYS

Adrian G
1/s 14/10/24
02 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: