

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	INCOME INSURAN	CE LTD	Ref:	CS/INC24100208/Uvh3m4	
	75 BRAS BASAH ROAD		Date:	24/10/2024	
	NCOME CENTRE SINGAPORE 189557		Code:	INC	
1.	1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJQ 2181P	Veh. Inspected	SMA 1458Y	
	Policy No.	-	Coverage	0	
	Claim No.	MT/1298863-002	Excess	\$0.00	
	Assign From	RAJESWARY	Assign Date	10/10/2024	
2.	2. Vehicle Details				
	Make & Model	HONDA VEZEL 1.5X AUTO	C.C	1496	
	Engine No.	L15B3522180	Year of Reg.	23/06/2015	
	Chassis No.	RU11022165	Colour	BLACK	
	Odometer	220912 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	215/60R16	MICHELIN	6	
	L/H Front Tyre	215/60R16	MICHELIN	6	
	R/H Rear Tyre	215/60R16	MICHELIN	6	
	L/H Rear Tyre	215/60R16	MICHELIN	6	
4.	4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.					
DAMAGES SEE DETAILS.					
5.	General Information				
	Accident Date	04/10/2024	Inspection Date	15/10/2024 (15:41)	
	Survey held at	WE GARAGE - 1 KAKI BUKIT AVE 6,	#02-11 AUTOBAY @	KAKI BUKIT, SINGAPORE 417883	
5a. Remarks					
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
•					

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days