



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

|  |       |                       |
|--|-------|-----------------------|
| MS AUTO & GENERAL INSURANCE (S) PL         | Ref:  | CS/AGI24100214/Avp3m4 |
| (BUDGET DIRECT INSURANCE)                  | Date: | 26/11/2024            |
| 190 CLEMENCEAU AVENUE #03-01               | Code: | AGI                   |
| SINGAPORE SHOPPING CENTRE SINGAPORE 239924 |       |                       |

### 1. Policy Particulars :- THIRD PARTY CLAIM

|              |              |                |            |
|--------------|--------------|----------------|------------|
| Insured Veh. | SJK 179S     | Veh. Inspected | YP 5028H   |
| Policy No.   | -            | Coverage       | 0          |
| Claim No.    | C10032183/MC | Excess         | \$0.00     |
| Assign From  | MONICA CHUNG | Assign Date    | 11/10/2024 |

### 2. Vehicle Details

|                 |                    |              |            |
|-----------------|--------------------|--------------|------------|
| Make & Model    | HINO XZU710R-HKFM3 | C.C          | 4009       |
| Engine No.      | N04CUS29474        | Year of Reg. | 19/12/2016 |
| Chassis No.     | JHHUCS3H40K018749  | Colour       | WHITE      |
| Odometer        | 312362 KM          | Steering     | IN ORDER   |
| Brakes          | IN ORDER           | General      | GOOD       |
| Modification(s) | RIMS: NIL          |              |            |

### 3. Conditions of Tyres

|                | Size    | Make | Balance (mm) |
|----------------|---------|------|--------------|
| R/H Front Tyre | 7.00R16 | GT   | 6            |
| L/H Front Tyre | 7.00R16 | GT   | 6            |
| R/H Rear Tyre  | 7.00R16 | GT   | 6            |
| L/H Rear Tyre  | 7.00R16 | GT   | 6            |

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

|                |  |                 |            |
|----------------|--|-----------------|------------|
| Accident Date  | 10/10/2024   | Inspection Date | 23/10/2024 |
| Survey held at | KT MOTORWERK<br>3012 BEDOK INDUSTRIAL PARK E, #01-2020, BEDOK INDUSTRIAL PARK E, SINGAPORE<br>489978 |                 |            |

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days