



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CS3/LPC24100234/Anh3m4
300 BEACH ROAD	Date:	08/11/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

### 1. Policy Particulars :- PRE-REPAIR SURVEY

Insured Veh.	XD 5375E	Veh. Inspected	SJD 3383K
Policy No.	-	Coverage	0
Claim No.	23/24/24/VC05/030011	Excess	\$0.00
Assign From	ERIC WOO	Assign Date	11/10/2024

### 2. Vehicle Details

Make & Model	MERCEDES BENZ B200	C.C	2035
Engine No.	26696030346678	Year of Reg.	26/12/2007
Chassis No.	WDD2452332J220971	Colour	MAROON
Odometer	146026 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/45R17	WEST LAKE	6
L/H Front Tyre	215/45R17	WEST LAKE	6
R/H Rear Tyre	215/45R17	WEST LAKE	6
L/H Rear Tyre	215/45R17	WEST LAKE	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	10/10/2024	Inspection Date	14/10/2024
Survey held at	SIN SENG HONG SPRAY PAINTING & SERVICES 3023A UBI ROAD 1 #01-63 SINGAPORE 408717		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days