REF:

ASSIGNMENT

From: Date:

Estn By Cost:

OD / TPIS / TP RES / OD RES / EVA / INV / MV

To in Vehicle No:

at W Pt m/s

of

Insured:

Policy No

Claims No

Sum Ins: Excess:

(Client Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SJD3383K Yr Regn: 2007, Dec

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Mercedes Benz B200 cc 2035

Colour: Maroon A/C: Insured / Std / NI / NA

Sp.Reading: 146026 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WDD2452332J220971

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/45R17 R: 215/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or Westlake

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	14/10/24

Survey held at Sin Hong Seng

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP LanPac (CPRS) COE Expiry: 31/10/2027.
	Estimate given during 1st Survey: Yes ( ) No (✓)
	MV: 33K (Depreciation @ 11K x 3yr ≈ 33K)
	PY: 15.41K
	Nett: 17.6K
	7782

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Preli. Report

☐ : Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($) ☐ : Interview ($) ☐ : Tech. Inve ($)

Survey Fee:	
Transportation:	
__S + RS.__SI	
Photos	
Others	

Report Format: