



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS LIBERTY INSURANCE PTE LTD		Ref:	CS/LAW24100238/Knh3m4	
C/O COMLAW LLC		64	Date:	28/10/2024
CECIL ST #06-01 IOB BLDG SINGAPORE 049711		Code:	LIP	
1. Policy Particulars :- THIRD PARTY CLAIM (PHYSICAL REINSPECTION)				
Insured Veh.	SKV 1111K	Veh. Inspected	SLW 4541R	
Policy No.	AVS24/0750	Coverage	0	
Claim No.	CLS 2027 228121	Excess	\$0.00	
Assign From	-	Assign Date	12/10/2024	
2. Vehicle Details				
Make & Model	AUDI A3 (A)	C.C	999	
Engine No.	CHZ640407	Year of Reg.	12/02/2018	
Chassis No.	WAUZZZ8VXJA072169	Colour	RED	
Odometer	25159 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: STANDARD ALLOY RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	205/55R16	MICHELIN	8	
L/H Front Tyre	205/55R16	MICHELIN	8	
R/H Rear Tyre	205/55R16	MICHELIN	8	
L/H Rear Tyre	205/55R16	MICHELIN	8	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS.				
REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	02/03/2024	Inspection Date	18/10/2024	
Survey held at	HIAP LEK AUTOMOBILE TRADING 160 SIN MING DRIVE #05-17 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				