

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliate data Fordonation Intermedianala Rea Funanta Fu Automobile				
Affiliated to Federation Internationale Des Experts En Automobile					
MS		INSURANCE (S) PL	Ref:	CS/AGI24100244/Avp3e2	
	(BUDGET DIRECT 190 CLEMENCEAU		Date:	22/11/2024	
		PPING CENTRE SINGAPORE 239924	Code:	AGI	
1.		Policy Particulars :- T	HIRD PARTY CLA	M	
	Insured Veh.	SGL 165L	Veh. Inspected	SDT 8080M	
	Policy No.	-	Coverage	0	
	Claim No.	C10032228/MC	Excess	\$0.00	
	Assign From	MONICA CHUNG	Assign Date	14/10/2024	
2. Vehicle Details					
	Make & Model	INFINITI Q50	C.C	1991	
	Engine No.	274AE078100A	Year of Reg.	23/11/2017	
	Chassis No.	JN1BCAV37Z0530107	Colour	GREY	
	Odometer	155464 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres					
		Size	Make	Balance (mm)	
	R/H Front Tyre	225/50 R18	DUNLOP	6	
	L/H Front Tyre	225/50 R18	DUNLOP	6	
	R/H Rear Tyre	225/50 R18	DUNLOP	6	
	R/H Rear Tyre L/H Rear Tyre	225/50 R18 225/50 R18	DUNLOP DUNLOP	6	
4.			DUNLOP		
	L/H Rear Tyre	225/50 R18	DUNLOP of Damages		
THE	L/H Rear Tyre	225/50 R18 Description of the DAMAGES AT THE FRONT PORTION OF THE PROPERTY OF	DUNLOP of Damages		
THE	L/H Rear Tyre VEHICLE SUSTAIN	225/50 R18 Description of the DAMAGES AT THE FRONT PORTION OF THE PROPERTY OF	DUNLOP of Damages ON.		
THE	L/H Rear Tyre VEHICLE SUSTAIN	225/50 R18 Description of ED DAMAGES AT THE FRONT PORTIONS.	DUNLOP of Damages ON.		
THE	L/H Rear Tyre VEHICLE SUSTAIN IAGES SEE DETAIL	225/50 R18 Description of ED DAMAGES AT THE FRONT PORTIONS. General Interpretations of the Company of the Com	DUNLOP of Damages ON. formation Inspection Date	14/10/2024	
THE	L/H Rear Tyre VEHICLE SUSTAIN IAGES SEE DETAIL Accident Date	Description of ED DAMAGES AT THE FRONT PORTIONS. General Into 13/10/2024 N-51 AUTOMOTIVE PTE LTD - 2 KAK	DUNLOP of Damages ON. formation Inspection Date I BUKIT AVE 2 #01-	14/10/2024	
THE DAM 5. 5a. A) T	L/H Rear Tyre VEHICLE SUSTAIN MAGES SEE DETAIL Accident Date Survey held at	225/50 R18 Description of ED DAMAGES AT THE FRONT PORTIONS. General Info 13/10/2024 N-51 AUTOMOTIVE PTE LTD - 2 KAK SINGAPORE 417921	DUNLOP of Damages ON. formation Inspection Date I BUKIT AVE 2 #01- arks EJUDICE" BASIS.	6 14/10/2024 17 KAKI BUKIT AUTOHUB	

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days