



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CS/LPC24100246/Uqh3m4
300 BEACH ROAD	Date:	19/11/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	YN 7812H	Veh. Inspected	GBF 7607Z
Policy No.	-	Coverage	0
Claim No.	24/24/24/VC05/030020	Excess	\$0.00
Assign From	ERIC WOO	Assign Date	14/10/2024

2. Vehicle Details

Make & Model	NISSAN NV200 1.5 MT	C.C	1461
Engine No.	K9KC400D056202	Year of Reg.	02/03/2017
Chassis No.	VSKYBAM20Z0137596	Colour	BLACK / SILVER
Odometer	293128 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: NIL		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	175/70R14	WINDFORCE	6
L/H Front Tyre	175/70R14	WINDFORCE	6
R/H Rear Tyre	175/70R14	WINDFORCE	6
L/H Rear Tyre	175/70R14	WINDFORCE	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S AND FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/10/2024	Inspection Date	15/10/2024
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days