



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24100249/Unh3e2
75 BRAS BASAH ROAD	Date:	24/10/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKA 191X	Veh. Inspected	SJW 8244X
Policy No.	-	Coverage	0
Claim No.	MT/1299649-001	Excess	\$0.00
Assign From	CHARLOTTE CHEW	Assign Date	15/10/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ E 250 (A)	C.C	1796
Engine No.	27186030043937	Year of Reg.	21/04/2010
Chassis No.	WDD2120472A183202	Colour	BLACK
Odometer	150761 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	245/35ZR19	PIRELLI	6
L/H Front Tyre	245/35ZR19	PIRELLI	6
R/H Rear Tyre	275/30ZR19	PIRELLI	6
L/H Rear Tyre	275/30ZR19	PIRELLI	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	09/10/2024	Inspection Date	15/10/2024 (10:38)
Survey held at	AUTOBACS CAR CARE (S) PTE LTD 8 KAKI BUKIT AVENUE 4 #08-40/45/46 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days