



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: ASTER QUEK

Ref: CS/INC24100250/Avh3m4(N)

Date: 23/01/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XE 8956D	Veh. Inspected	GBG 1184K
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1298953-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	15/10/2024

2. Vehicle Particulars & Condition

Make & Model	NISSAN NV200	c.c	1461
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	VSKYBAM20Z0144510	Colour	SILVER
Odometer	136517 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	175/70R14C	WEST LAKE	6 mm
L/H Front Tyre	175/70R14C	WEST LAKE	6 mm
R/H Rear Tyre	175/70R14C	WEST LAKE	6 mm
L/H Rear Tyre	175/70R14C	WEST LAKE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	08/10/2024	Inspect Date / Time	15/10/2024 (02:38 PM)
Survey held at	HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **5 Working Days**