

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT					
	INCOME INSURAN		Ref:	CS/INC24100251/Aqh3m4(N)	
	75 BRAS BASAH R INCOME CENTRES		Date:	28/01/2025	
	ATTN: ENG HUEY	HUEY		Code:	INC
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJT 4979B	Veh. Inspected	t	SNS 7535L
	Policy No.		Coverage (\$)		0.00
	Claim No.	MT/1299718-002	Excess (\$)		0.00
	Assign From	HAZALYSA BINTE IBRAHIM	Assign Date		15/10/2024
2. Vehicle Particulars & Condition					
	Make & Model	PORSCHE PANAMERA S	c.c		4806
	Engine No.	HIDDEN	Year of Reg.		2010
	Chassis No.	WP0ZZZ97ZAL045824	Colour		WHITE
	Odometer	136430 KM	Steering		IN ORDER
	Brakes	IN ORDER	Modification		SPORTS RIM
	General	GOOD			
3. Conditions of Tyres					
		Size	Make		Balance
	R/H Front Tyre	295/35R20	PIRELLI		6 mm
	L/H Front Tyre	295/35R20	PIRELLI		6 mm
	R/H Rear Tyre	295/35R20	PIRELLI		6 mm
	L/H Rear Tyre	295/35R20	PIRELLI		6 mm
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	12/10/2024	Inspect Date /	Time	15/10/2024 (03:04 PM)
	Survey held at	JL PERFECT AUTOWORK PTE	LTD		
	8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORM	MAL PERIOD FOR REPAIR:		12 Work	ing Days