



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: YEE PEI LI

Ref: CS/INC24100252/Avh3m4(N)

Date: 24/01/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLG 9754U	Veh. Inspected	SDU 9898J
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1299108-002	Excess (\$)	0.00
Assign From	HAZALYSA BINTE IBRAHIM	Assign Date	15/10/2024

2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1797
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZVW506042390	Colour	SILVER
Odometer	258529 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65R15	MICHELIN	6 mm
L/H Front Tyre	195/65R15	MICHELIN	6 mm
R/H Rear Tyre	195/65R15	MICHELIN	6 mm
L/H Rear Tyre	195/65R15	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	10/10/2024	Inspect Date / Time	15/10/2024 (02:49 PM)
Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **6 Working Days**