

ASSIGNMENT

From: _____ Date: _____

Estn: _____

OD / TP RES / CD RES / EVA / INV / MV

To in Vehicle No: _____

at W/O / TP / INV / S

of _____

Insured: _____

Policy No: _____

Claim's No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Val: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SDU 9898J Yr Regn: 2017, July

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius C.S. 1797

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 258529 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2VW 506042390

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 15/10/24

*Survey held at JL Perfect.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>TP INC</u>
	<u>COE Expiry</u>
	<u>Estimate given during : Yes (✓)</u>
	<u>1st Survey : No ()</u>
	<u>MV :</u>
	<u>PV :</u>
	<u>Nett :</u>
	<u>184K</u>

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1) Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$ _____)

Survey Fee: _____

Transportation: _____

Report Format: _____

Report Format: _____

☐ : Interview (\$ _____)

Photos _____

☐ : Tech. Insp (\$ _____)

Others _____

☐ : _____