

(08/11/13) wef

REF:

CS/AG/24100253/Unp3

ASS. REC. BY: Marcus

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 1/R 2923H

at Workshop m/s Think one 2pm

of _____

Insured: SMN 9116T

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \$118k

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lum Sum: 1.3.1 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

C 609m

Vehicle: IN / OUT

Date: _____ Person Contacted: 27A 69101

Veh No: 1/R 2923H Yr Regn: 31/07/24

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or Car

Make: HINO / X2U 710R c.c. 4009

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 3392 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHHUCV3F70K057416

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/80R15

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front Rear

R/Bal. mm R/Bal. mm

L/Bal. mm L/Bal. mm

D.O.A. 07/09/24 D.O.I. 16/10/24

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

13-11-24 Submit P/P & SVO vehicle hasn't send in for repair

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$)

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	609M
Vehicle Details	
Vehicle No.:	YR2923H
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Oct 2024
Vehicle Make:	HINO
Vehicle Model:	XZU710R 14FT WID CAB 5T MT
Primary Colour:	White
Manufacturing Year:	2024
Engine No.:	N04CWN28670
Chassis No.:	JHHUCV3F70K057416
Maximum Power Output:	-
Open Market Value:	\$25,920.00
Original Registration Date:	31 Jul 2024
First Registration Date:	31 Jul 2024
Transfer Count:	0
Actual ARF Paid:	\$1,296.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jul 2034
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$70,601.00
COE Rebate Amount:	\$69,101.00
Total Rebate Amount:	\$69,101.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 16 Oct 2024

OK



Home Used Cars Listing

All Category



Search

Save Search



2024 X

23 Vehicles

Car Make

Car Model

Price Range

Depreciation

2024

Mileage



PREMIUM AD

Hino XZU710R

\$127,800

Instl. \$1,684 /mth

\$12,790 /yr

11-Oct-2024

(9yrs 11mths COE left)

N.Air 4,009 cc 1 Owner Diesel



New Hino 14 feet truck, warranty by agent, 3yrs/100k km warranty, we accept trade in, contact us now to find out about this new lorry.

Ezy-1 Pte Ltd|Posted 14-Oct-2024

☐ Compare

PREMIUM AD

Hino XZU710R

\$127,800

Instl. \$1,684 /mth

\$13,640 /yr

26-Feb-2024

(9yrs 4mths COE left)

N.Air 4,009 cc 1 Owner Diesel



New agent unit! Can be customized to suit any business activities. Call our friendly sales representative to find out more!

Ezy-1 Pte Ltd|Posted 14-Oct-2024

☐ Compare

PREMIUM AD

Hino XZU710R

\$122,888

Instl. \$1,619 /mth

\$12,430 /yr

04-Sep-2024

(9yrs 10mths COE left)

N.Air 4,009 cc 1 Owner Diesel



New Hino 14ft lorry, warranty by agent, all attachment available for you to customize to your business needs, front back camera, call us for more details, cheapest in the market.

Lek Auto Pte Ltd|Posted 14-Oct-2024

☐ Compare

Compare



THINK ONE AUTOCARE PTE LTD

RCB : 201322501G GST : 201322501G
80 JALAN LAM HUAT, #02-32 CARROS CENTRE, SINGAPORE 737889
Tel: (65)6844 3300/ (65)6545 3300 Fax: (65)6842 4988/ (65)6256 1284
Email: enquiry_autocare@thinkone.com.sg

ESTIMATED

Vehicle Plate No: YR2923H

Date: 09/10/2024

Make & Model: HINO XZU710R

Chassis No: JHHUCV3F70K057416

NO	PARTICULAR	QTY	UNIT/PRICE	AMOUNT S\$
1	SIDEGATE RH	1	R	3,500.00 X

No LABOUR & MISCELLANEOUS:

- | | | | |
|---|--|--------|-----|
| 1 | To remove damaged body parts with all necessary components/attachments apply hot-works where necessary repair, reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components/attachments | 350.00 | 200 |
| 2 | To spray paint replaced/repaired body parts inclusive of preparatory works and painting materials | 400.00 | 300 |

Not Authorized
in
morans
16/10/24
P/P \$500/
2 days.
Take photo After repair

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: