

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? ..... No  
 Was notice of intended Prosecution given? ..... No  
 If yes, against whom? ..... -

#### CIRCUMSTANCES OF ACCIDENT

According to BC: Bus was stationary complying with traffic lights when rear portion of bus was being hit by front portion of 3P lorry. 3P lorry driver fainted and was attended by paramedics. But said 3P lorry driver refused to be conveyed to hospital.

#### ATTACHMENT(S)

Are accident photos available for attachment? ..... No  
 Was there any video captured by Car Camera? ..... Yes  
 Reasons for not uploading a video of the accident ..... Confidential.

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number ..... YN9420S  
 Vehicle Manufacturer ..... -  
 Vehicle Model ..... -  
 Vehicle Variant ..... -  
 Vehicle Colour ..... -  
 Vehicle Category ..... Goods vehicle  
 Name of Driver ..... -  
 Contact Number ..... -  
 Address ..... -  
 Address complement ..... -  
 Postcode ..... -  
 Insurance Company Name ..... -  
 Nature Of Damage ..... -  
 Details of property damaged in accident ..... -  
 No. Of Passenger (Including Driver) ..... -

#### INJURED PERSONS DETAILS

##### INJURED 1

Name of injured person ..... Yeo Chun Boon  
 Gender ..... Male  
 Phone No ..... (Phone) +65-93448779  
 Address ..... -  
 Address Complement ..... -  
 Post Code ..... -  
 Approximate Age Years Old ..... -  
 Injuries Sustained ..... Fainted  
 Injured person in which vehicle? ..... YN9420S  
 Were seat belts worn? ..... No  
 Was this injured conveyed to hospital by ambulance? ..... No



## SKETCH PLAN

BC NUMBER: 88086

SVC NUMBER: 268

BUS PLATE NUMBER: 6568 R

DATE OF ACCIDENT: 10/10/2024

TIME OF ACCIDENT: 10.02

For DSO

AR NUMBER: AR-2024-5567

FMP NUMBER:

BC SIGNATURE: 

Ang Mo Kio Ave 5

Ang Mo Kio Ave 2

