

REF:

ASSIGNMENT

Front: _____ Date: _____

Estimate: _____

OD / TP / TP RES / CD RES / EVA / INV / MVTo in Vehicle NO: _____at W/O 10/10/10 m/s _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vch: _____

(Policy Condition)

N/S	O/S

Remark: There had commenced its
repair at the time of inspection.

Bal. or Metal Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SKG276D Yr Regn: 2012 JuneType: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Porsche Panamera C.D. 360SColour: Bronze A/C: Insured / Std / NI / NASp. Reading: 178467 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WPOZZZ97-ZCL002559Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim orTyre Size: F: 295/40R19R: 295/40R19BS / DUN / EXNOVA / GY / FS / LIZA / WIC / QHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 29/10/24Survey held at N51Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP ChiniCOE Expiry: 05/06/2032

Estimate given during: Yes (✓)

1st Survey: No ()

MV: 125KPV: 72.3KNett: 52.7K

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation:

3 + R.S. \$1

Photos

Others

1) _____
Date/Time, File Return to?☐ : Final Report

2) _____

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Inve (\$)

Report Format: _____

Report Form: _____