



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD  
INCOME CENTRESINGAPORE 189557

ATTN: MARCUS XIAO

Ref: CS/INC24100265/Avh3m4(N)

Date: 02/01/2025

Code: INC

#### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBL 2153S	Veh. Inspected	SLP 1489R
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1299349-002	Excess (\$)	0.00
Assign From	MARCUS XIAO	Assign Date	15/10/2024

#### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA VOXY	c.c	1986
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	ZRR800258622	Colour	SILVER
Odometer	240709 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

#### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	NEXEN	6 mm
L/H Front Tyre	215/55 R17	NEXEN	6 mm
R/H Rear Tyre	215/55 R17	NEXEN	6 mm
L/H Rear Tyre	215/55 R17	NEXEN	6 mm

#### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.  
DAMAGES SEE DETAILS.

#### 5. General Information

Accident Date	11/10/2024	Inspect Date / Time	15/10/2024 ( 05:37 PM )
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

#### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

#### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days