

(08/11/13) WFL

ASS. REC. BY:

REF:

CD/LPC24100281/Xpa3

0334

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: 4P9630S

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

REPAIR LIMIT - 67K

Veh No:

4P9630S

Yr Regn:

2018 / SEP

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

ISUZU FVR90SU

cc 5193

Colour:

WHITE

AC: Insured / Std / NI / NA

Sp. Reading:

268057

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JALFVR907J7000006

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

275/70R22.5

R:

BS / DUN / EXNOVA / GY / FS / LZA / MC / OHTSU / PIR / SUMI /

TOYO / YOKO or

ROADSTAR

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

15/10/26

D.O.I.

29/10/26

Survey held at

FAN YOUNG

Des. of Damages: Frt / Rear / O/S / N/S / WC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File From Int

☐
☐

Prell. Report

Final Report

1)

Date/Time, File Return Int

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format:

Lump Sum / L.B.L. (\$)

Add Fee:

☐
☐
☐
☐

Site Insp (\$

Interview (\$

Tech. Invs (\$

Weekend (\$

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



Automotive Pte Ltd

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel : (65) 6476 3333
Fax : (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel : (65) 6272 3892
Fax : (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

ESTIMATE

16/10/2024

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

Vehicle No: YP9630S
Vehicle Model: ISUZU FVR90SUQDC
Est No: CBMW24100093
Claims ref:
Accident Date: 15/10/24
In Charge: BRIAN
Remarks:

No	Description	Qty	U. Price	Amounts S\$
LIST ITEMS:				
1	TAILLAMP RH <i>cm</i>	1	PC \$ 385.00	\$ 385.00
LIST TOTAL S\$				\$ 385.00
15% DISCOUNT S\$				\$ (57.75)
				<u>\$ 327.25</u>

SPECIAL NET ITEMS:				
1	TAILGATE PLATFORM ROLLER <i>cm</i>	1	PC \$ 55.00	\$ 55.00
2	TAILGATE PLATFORM ROLLER SKIM PLATE <i>bl</i>	1	PC \$ 50.00	\$ 50.00
3	TAILGATE LIFT CYLINDER LH/RH ?	2	PC \$ 2,800.00	\$ 5,600.00
4	TAILGATE TILT CYLINDER LH/RH ?	2	PC \$ 2,800.00	\$ 5,600.00
5	REFLECTIVE STICKER <i>2ea</i>	1	PC \$ 40.00	\$ 40.00
6	HYDRAULIC FLUID ?	1	PC \$ 120.00	\$ 120.00
7	LITHIUM GREASE ?	1	PC \$ 60.00	\$ 60.00

SPECIAL NET TOTAL S\$ \$ 11,525.00

LABOUR CHARGE:			
1	TO SPRAY PAINT ON PLATFORM BRKT AND AFFECTED AREAS	\$	250.00 100
2	TO REPLACE TILT CYLINDER AND LIFT CYLINDER	\$	550.00 300?
3	TO REMOVE & REFIT TAILGATE PLATFORM TO ASSIST REPAIR	\$	450.00 200
4	TO ADJUST TAILGATE TOLERANCE, BOTH UP-DOWN & FORE AFT	\$	650.00 350
5	TO CALIBRATE THE TAILGATE SYSTEM & LOAD TEST	\$	750.00 350
TOTAL LABOUR COST S\$			<u>\$ 2,650.00</u>

AMOUNT S\$ \$ 14,502.25
GST @ 9% \$ 1,305.20
AMOUNT DUE S\$ \$ 15,807.45

Customer's Signature

MOVA AUTOMOTIVE PTE LTD



Isuzu FVR90

\$122,800 Instalment \$1,904/mth

Shortlist

Loan Calculator



Overview Financial Photo Research

Depreciation	<i>i</i> \$21,030 / year
Reg. Date	01-Sep-2020 (5yrs 10mths 1day COE left)
Lifespan	<i>i</i> 31-Aug-2040
Manufactured	<i>i</i> 2020
Mileage	5,900 km (1.4k / year)
Transmission	Auto
Engine Cap	5,193 cc
Curb Weight	<i>i</i> 11,120 kg
Fuel Type	Diesel
COE	<i>i</i> \$24,502
OMV	<i>i</i> \$72,085
ARF	<i>i</i> \$3,605
Dereg Value	<i>i</i> \$14,305 as of today
No. of Owners	<i>i</i> 2
Type of Veh	Truck

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	033G
Vehicle Details	
Vehicle No.:	YP9630S
Vehicle to be Exported:	No
Intended Deregistration Date:	30 Oct 2024
Vehicle Make:	ISUZU
Vehicle Model:	FVR90SUQDC AMT
Primary Colour:	White
Manufacturing Year:	2018
Engine No.:	4HK1732947
Chassis No.:	JALFVR907J7000006
Maximum Power Output:	-
Open Market Value:	\$68,432.00
Original Registration Date:	21 Sep 2018
First Registration Date:	21 Sep 2018
Transfer Count:	0
Actual ARF Paid:	\$3,422.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	20 Sep 2028
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$30,389.00
COE Rebate Amount:	\$11,826.00
Total Rebate Amount:	\$11,826.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 30 Oct 2024

OK