



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24100282/Rnp3m4
(BUDGET DIRECT INSURANCE)	Date:	27/11/2024
190 CLEMENCEAU AVENUE #03-01	Code:	AGI
SINGAPORE SHOPPING CENTRE SINGAPORE 239924		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMM 6345T	Veh. Inspected	SKT 5312G
Policy No.	P10599460R03	Coverage	0
Claim No.	C10032179/KR	Excess	\$0.00
Assign From	KAVIDHA RAJAN	Assign Date	16/10/2024

### 2. Vehicle Details

Make & Model	TOYOTA COROLLA ALTIS 1.6L	C.C	1598
Engine No.	1ZRX514143	Year of Reg.	12/06/2015
Chassis No.	MR053REH104533898	Colour	GREY
Odometer	314613 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	205/55R16	PIRELLI	6
L/H Front Tyre	205/55R16	PIRELLI	6
R/H Rear Tyre	205/55R16	PIRELLI	6
L/H Rear Tyre	205/55R16	PIRELLI	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	10/10/2024	Inspection Date	18/10/2024
Survey held at	AVANTAGE AUTOMOBILES PTE LTD - 48 TOH GUAN ROAD EAST, #05-136, ENTERPRISE HUB, SINGAPORE 608586		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days