

5b.

ESTIMATED NORMAL PERIOD FOR REPAIR: 14 Working Days

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	nale Des Experts En	Automobile
MS	LONPAC INSURAN	ICE BHD	Ref:	CS/LPC24100298/Evh3e2
	300 BEACH ROAD		Date:	16/12/2024
	#17-04/07 THE CO	NCOURSE SINGAPORE 199555	Code:	LPC2
1.	Policy Particulars :- THIRD PARTY CLAIM			
	Insured Veh.	XD 2810K	Veh. Inspected	SDT 9338P
	Policy No.	Z24VC05022370	Coverage	0
	Claim No.	24/24/24/VC05/030014	Excess	\$0.00
	Assign From	ERIC WOO	Assign Date	16/10/2024
2.	Vehicle Details			
	Make & Model	TOYOTA COROLLA ALTIS	C.C	1598
	Engine No.	1ZRX516414	Year of Reg.	15/06/2015
	Chassis No.	MR053REH104534555	Colour	GREY
	Odometer	290036 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: SPORTS RIM	•	
3.	Conditions of Tyres			
		Size	Make	Balance (mm)
	R/H Front Tyre	205/55 R16	ARIVO	4
	L/H Front Tyre	205/55 R16	ARIVO	4
	R/H Rear Tyre	205/55 R16	ARIVO	4
	L/H Rear Tyre	205/55 R16	ARIVO	4
4.	Description of Damages			
ΗE	VEHICLE SUSTAIN	IED DAMAGES AT THE REAR PORT	ION.	
ΑN	IAGES SEE DETAIL	.S.		
5. General Information				
	Accident Date	11/10/2024	Inspection Date	17/10/2024
	Survey held at TWIN WHEELS AUTO TRADING ENTERPRISE - 38 WOODLANDS ROAD #03-14, WOODLANDS INDUSTRIAL PARK E1 SINGAPORE 757700			
5a.		Re	marks	
		AS CONDUCTED ON A"WITHOUT PI D YOUR INSTRUCTIONS, WE HAVE		REPAIRS

Estimate Days of Repair