Assg. No.: REF:

ASSIGNMENT

From: Date:

Estim. Cost:

OD / TPBI / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at WO / Workshop/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client Record)

Make of Veh.

(Policy Condition)

Veh No: SNN3651L Yr Regn: 2023, NOV

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or

Make: Toyota Sienta C.C. 1490

Colour Grey A/C: Insured / Std / NI / NA

Sp.Reading 46919 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MXPL1010479 33

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: 185/65R15

	N/S	O/S
Remark: The veh had commenced its repair at the time of inspection.		

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front		Rear	
R/Bal.	06 mm	R/Bal.	06 mm
L/Bal.	06 mm	L/Bal.	06 mm
D.O.A.		D.O.I.	17/10/24

Survey held at MG Solution

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or Rear O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TP INC
	MV :
	PV :
	Nett :

COE Expiry :

Estimate given during 1st Survey : Yes (✓) No ( )

Date/Time, File Pass to? ☐ : Preli. Report

1) ☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee: ☐ : Site Insp ($)

☐ : Interview ($)

☐ : Tech. Inve ($)

Survey Fee:

Transportation: S + P.S. SI

Photos

Others

Report Format :

Remarks / Ref. No.