



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

INCOME INSURANCE LTD

75 BRAS BASAH ROAD
INCOME CENTRESINGAPORE 189557

ATTN: YEE PEI LI

Ref: CS/INC24100302/Avh3e2(N)

Date: 27/01/2025

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMW 1611E	Veh. Inspected	SLV 1294D
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1299990-002	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	17/10/2024

2. Vehicle Particulars & Condition

Make & Model	NISSAN QASHQAI	c.c	1197
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	SJNFEAJ11U2150288	Colour	SILVER
Odometer	66925 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R17	FALKEN	6 mm
L/H Front Tyre	215/60 R17	FALKEN	6 mm
R/H Rear Tyre	215/60 R17	FALKEN	6 mm
L/H Rear Tyre	215/60 R17	FALKEN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/10/2024	Inspect Date / Time	17/10/2024 (12:32 PM)
Survey held at	JL PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **7 Working Days**