



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS INCOME INSURANCE LTD	Ref:	CS/INC24100303/Uvh3e2
75 BRAS BASAH ROAD	Date:	28/10/2024
INCOME CENTRE SINGAPORE 189557	Code:	INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBN 2325C	Veh. Inspected	SMM 2629B
Policy No.	-	Coverage	0
Claim No.	MT/1297325-002	Excess	\$0.00
Assign From	EILEEN LEE	Assign Date	17/10/2024

2. Vehicle Details

Make & Model	B.M.W. X1 SDRIVE (A)	C.C	1499
Engine No.	43735648B38A15A	Year of Reg.	24/06/2019
Chassis No.	WBAJG120705N13071	Colour	GREY
Odometer	64979 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/55R17	MICHELIN	6
L/H Front Tyre	225/55R17	MICHELIN	6
R/H Rear Tyre	225/55R17	MICHELIN	6
L/H Rear Tyre	225/55R17	MICHELIN	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	21/09/2024	Inspection Date	17/10/2024 (10:54)
Survey held at	JUZZ PERFORMANCE PTE LTD 8 KAKI BUKIT AVENUE 4 #03-51/52 PREMIER @ KAKI BUKIT SINGAPORE 415875		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days