

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/INC 24100303/4vh3**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SMM 2629B

at Workshop m/s

Just Performance

of

Insured:

FBN 2325C

Policy No.

Claims No. MT/1297325-002


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: **The veh had commenced its repair at the time of inspection.**

Bal. or Market Value:

\$96k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4  
20

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

**CA / REV / REP. / 24 HRS**01461

Date:

Person Contacted:

Vehicle: IN / OUT

LTAS 46226

Veh No:

SMM 2629B

Yr Regn:

24/46/19Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA /

Make:

BMWXSDRIVE.c1499

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

64979

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WBAJG 120705-N / 3071Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

225/55 R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

21/09/24

D.O.I.

17/10/24

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orN/S RearThe U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Dep 16k.

24/10/24 have video of folder  
4/5 \$3000 in hand Answer (red 8334.72, 73%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

### Vehicle Owner Particulars

Owner ID Type: Singapore NRIC  
Owner ID: 014G

### Vehicle Details

Vehicle No.: SMM2629B  
Vehicle to be Exported: No  
Intended Deregistration Date: 17 Oct 2024  
Vehicle Make: B.M.W.  
Vehicle Model: X1 SDRIVE18I LED NAV  
Primary Colour: Grey  
Manufacturing Year: 2019  
Engine No.: 43735648B38A15A  
Chassis No.: WBAJG120705N13071  
Maximum Power Output: 103.0 kW (138 bhp)  
Open Market Value: \$35,726.00  
Original Registration Date: 24 Jun 2019  
First Registration Date: 24 Jun 2019  
Transfer Count: 0  
Actual ARF Paid: \$42,017.00 21038

### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 23 Jun 2029  
PARF Rebate Amount: \$29,411.00

### Intended COE Rebate Details

COE Expiry Date: 23 Jun 2029  
COE Category: E - Open - all except motorcycle  
COE Period(Years): 10  
QP Paid: \$39,400.00  
COE Rebate Amount: \$16,815.00  
**Total Rebate Amount: \$46,226.00**

### Message

You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.

The information contained herein is correct as at 17 Oct 2024

OK





Home Used Cars-Listing

All Category



Search

Save Search



Any status X 2019 X

Sort by Any Status, Date Posted (Newest)

52 Vehicles

Car Make

Car Model

Price Range

Depreciation

2019

Mile



PREMIUM AD

BMW X1 sDrive18i

xLine

\$99,800

Instl. \$1,438  
/mth

\$16,900 /yr

1 Owner

29-May-2019

(4yrs 7mths COE left)

71,000 km

1,499 cc



1 owner! Fully agent maintained! Powerful and responsive, yet returning excellent fuel efficiency. Spacious cabin and boot space. Extremely well maintained. Superb condition from interior to exterior. View to believe. Very flexible loan schemes available. View to appreciate.

Trust Motoring Capital Pte Ltd|Posted 17-Oct-2024

☐ Compare

PREMIUM AD

BMW X1

sDrive18i

\$110,800

Instl. \$1,498  
/mth

\$18,030 /yr

1 Owner

23-Sep-2019

(4yrs 11mths COE left)

50,000 km

1,499 cc



1 owner! PML unit! Agent maintained since day 1 until now! View to believe! Free 2 years warranty with 10 servicing provided! The BMW X1 sDrive18i give you highs sweetheart engine and transmission, athletic chassis and capacious cargo hold.High trade in up to \$3k. Contact us for viewing now!

Dynamic Motoring|Posted 15-Oct-2024

☐ Compare

PREMIUM AD

BMW X1 sDrive18i

xLine

\$101,800

Instl. \$1,420  
/mth

\$16,960 /yr

1 Owner

23-Jul-2019

(4yrs 9mths COE left)

73,000 km

1,499 cc



1 Owner! Fully Agent Maintained! Powerful And Responsive, Yet Returning Excellent Fuel Efficiency. Spacious Cabin And Boot Space. Extremely Well Maintained. Superb Condition From Interior To Exterior. View To Believe. Very Flexible Loan Schemes Available. View To Appreciate.

Trust Motoring Capital Pte Ltd|Posted 15-Oct-2024

☐ Compare

Compare

Estimate Cost Of repair: SMM2629B

Vehicle Model: F48/X1

WBAJG120705N13071

Spare Part:

Rear Bumper Panel	CUT ✓	\$	964.30 ✓
Insert Panel	711 X	\$	148.00 X
Tow cover	11 X	\$	63.00 X
Cover bumper	LOW CUT ✓	\$	312.00 ✓
1 set Rivet and screw:	121 30 S/N	\$	150.00 30 S/N
Rear left side taillight lens	tail lamp CR ✓	\$	434.90 ✓
Rear left side fender	2X	\$	3,548.15 X
<b>Rear Left door-dent</b>	2X	\$	<b>1,315.90 X</b>
Rear wheel arch left	CUT ✓	\$	173.80 ✓
rear bumper reflector	1H CR ✓	\$	554.67 ✓
Labour		\$	7,110.05
Sub Total (5%)			
To check electrical wiring and connector		\$	150.00 20
To rear left door	11	\$	370.00 X
To replace rear bumper and attachment parts		\$	300.00
To replace rear left fender include cut and weld		\$	1,600.00 } 680
To left rear wheel arch		\$	230.00
To respray three panel include putty		\$	900.00 600

**SUB TOTAL**

\$ 3,550.00

**GRAND TOTAL**

\$ 10,660.05

Rocker panel lower side skirt 1H \$ 620.00 700 ✓

not pulled  
the  
meant

9009 6608

H by S

17/10/24

1/5 \$ 3000

LKK Auto Consultants hence notify  
the Repairer of the following:

- To survey before/after spray painting
- To display damaged part(s) before survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-surveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P- 2559.67  
52  
P- 2431.69  
S.N- 30  
L- 1300  
3761.69  
202  
3002