

(08/11/13) Wef

ASS. REC. BY:

REF:

CS/CTI24060022/Rvp3

CASE-2406022

3420

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SMH 7750B

at Workshop m/s Ewokars

of Thompson. P

Insured: XE 3329Y CTI

Policy No.

Claims No. SNM24D203313

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

88k

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SMH 7750B

Yr Regn: 2019 JAN

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

MINI ONE 3DR HB (LCI)

c.c 1499

Colour:

GREY

A/C: Insured / Std / NI / NA

Sp. Reading:

38959

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WMWXR120507687881

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/55R16

R:

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

HANKOOK

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

05/06/24

D.O.I.

10/06/24

Survey held at

Ewokars

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REPAIR LIMIT-62K

25/9/24

Submit preli report-revised fig \$7339.51 check items \$4188

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: 5

1)

☐

Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐

Site Insp (\$

) \$ + RS \$

☐

Interview (\$

) Photos

☐

Tech. Invs (\$

) Others

☐

Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

REPAIR ESTIMATE

Name & Address:

Motor Claims Department

CHINA TAIPING INSURANCE P/L

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Email/Fax No:

Contact No:

Vehicle No:

SMH7750B

Brand & Model:

MINI One Hatch RHD

Chassis/VIN No:

WMWXR12050TE87881

WIP#:

24720

Date:

6-Jun-24

Franchise:

MINI

Contact Person (Eurokars):

FAISAL

Contact No (Eurokars):

6331 0680

Type of Claim:

THIRD PARTY

YEAR MODEL:

31/01/2019

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	FRONT WINDSCREEN <i>bro /</i>	M51.31.7.443.871	1		-	\$ 965.18
2	REPAIR FLAT WINDSCREEN <i>nw /</i>	M83.19.2.289.285	1		-	\$ 200.20
3	BUMP STOP <i>nw /</i>	B51.31.7.288.462	6		-	\$ 28.50
4	CLEANER R1 <i>nw /</i>	B83.19.2.211.217	1		-	\$ 47.13
5	SOUND INSULA <i>nw /</i>	B51.48.7.325.890	1		-	\$ 140.34
6	LEFT COLUMN <i>nw /</i>	M51.13.7.300.007	1		-	\$ 142.00
7	RIGHT COLUMN <i>nw /</i>	M51.13.7.300.008	1		-	\$ 142.00
8	BONNET CHROME GARNISH <i>cut /</i>	M51.13.7.424.554	1		-	\$ 269.42
9	BONNET <i>bt /</i>	M41.00.8.499.868	1		-	\$ 1,529.12
10	TRIM RING, HEADLIGHT LH <i>nw /</i>	M51.13.7.300.631	1		-	\$ 101.79
11	TRIM RING, HEADLIGHT RH <i>nw /</i>	M51.13.7.300.632	1		-	\$ 101.79
12	TRIM RING CLIP <i>nw /</i>	M51.13.2.752.145	12		-	\$ 48.36
13	MINI EMBLEM <i>nw /</i>	M51.14.9.447.805	1		-	\$ 83.78
14	LABEL, COOLANT <i>nw /</i>	M71.23.6.992.810	1		-	\$ 34.90
15	DASHBOARD <i>?</i>	M51.45.9.378.968	1		-	\$ 2,348.00
16						\$ -

Sub-Total (Parts Price) \$ - \$ 6,182.51

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
		920	
1	TO REMOVE /REPLACE DAMAGED FRONT BONNET. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	960	\$ 1,840.00
2	TO RESPRAY FRONT BONNET	960	\$ 1,100.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.	150	\$ 250.00
4	TO REMOVE & REFIT THE FRONT / REAR WINDSCREEN GLASS.	nett	\$ 560.00
5	TO SUPPLY SEALER ON THE FRONT / REAR WINDSCREEN GLASS.	nett	\$ 195.00

REPAIR ESTIMATE

6	TO SUPPLY SOLAR FLIM ON THE FRONT / REAR WINDSCREEN GLASS.	nett	\$ 300.00
7	TO REMOVE & REPLACE DASHBOARD ASSY ? photo	nett	\$? 1,840.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150	\$ 250.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	nett	\$ 250 350.00
10	SUNDRIES.	nett	\$ 20 50.00

Survey Date & Time: 10/06/24	Repair Days: 5 days	Excess:
---------------------------------	------------------------	---------

Surveyor Remarks:

Remove
4x 9001068
Reg 64 paint

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- An administrative fee of 20% of the quotation value will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price) \$ - \$ 6,735.00

	REVISED	PRICE
Parts Price	\$ -	\$ 6,182.51
Labour Price	\$ -	\$ 6,735.00
Total (Initial Estimate)	\$ -	\$ 12,917.51
Supp 1	\$ -	\$ -
Supp 2	\$ -	\$ -
Supp 3	\$ -	\$ -
Total (Before Excess)	\$ -	\$ 12,917.51
Less Excess	\$ -	\$ -
TOTAL (After Excess)	\$ -	\$ 12,917.51
GST 9%	\$ -	\$ 1,162.58
GRAND TOTAL	\$ -	\$ 14,080.09

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	342D
Vehicle Details	
Vehicle No.:	SMH7750B
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Jun 2024
Vehicle Make:	MINI
Vehicle Model:	ONE 3DR HB (LCI)
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	F738K011B38A15A
Chassis No.:	WMWXR12050TE87881
Maximum Power Output:	75.0 kW (100 bhp)
Open Market Value:	\$25,294.00
Original Registration Date:	31 Jan 2019
First Registration Date:	31 Jan 2019
Transfer Count:	1
Actual ARF Paid:	\$17,412.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Jan 2029
PARF Rebate Amount:	\$12,188.00
Intended COE Rebate Details	
COE Expiry Date:	30 Jan 2029
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$28,199.00
COE Rebate Amount:	\$13,068.00
Total Rebate Amount:	\$25,256.00
Message	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 11 Jun 2024

OK

MINI One 1.5A

\$80,800 Instalment \$1,295/mth

PREMIUM AD

Shortlist

Get Warranty

Loan Calculator

TRENDING NOW

mycarforum

2024 Volvo EM90

Overview Financial Photo Research

Depreciation	\$17,660 / year
Reg. Date	30-Jul-2018 (4yrs 1mth 18days COE left)
Manufactured	2018
Mileage	49,999 km (8.5k / year)
Transmission	Auto
Engine Cap	1,499 cc
Road Tax	\$684 / year
Power	75.0 kW (100 bhp) View specs of the MINI One (2019-2024)
Curb Weight	1,140 kg
COE	\$32,699
OMV	\$24,006
ARF	\$15,609
Dereg Value	\$24,445 as of today