

ASS. REC. BY:

REF:

U02/ CS/ U0124100307/ knp3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/LMV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

1.34 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SIF-8263R

Yr Regn:

06, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Lexus

ES250

c.c

2494

Colour

M. Blue

A/C: Insured / Std / NI / NA

Sp. Reading

98466

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

J711BJ1G6-10-2095704

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / A/Rim or

Tyre Size:

F:

215/55R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

15/10/24

D.O.I.

17/10/2024

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

197 O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

22/11

4816.00

Cash

(Red. \$ 50, 1%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

200

Transportation:

60

S + RS. SI

80+80

Fees

26

Others

TOTAL

446

Report Format :

Lump Sum / I.B.I: (\$