



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS AUTO & GENERAL INSURANCE (S) PL	Ref:	CS/AGI24100308/Eqp3e2
(BUDGET DIRECT INSURANCE)	Date:	07/11/2024
190 CLEMENCEAU AVENUE #03-01		
SINGAPORE SHOPPING CENTRE SINGAPORE 239924	Code:	AGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SMH 8310G	Veh. Inspected	JVJ 565
Policy No.	P10504500R03	Coverage	0
Claim No.	C10031746/MC	Excess	\$0.00
Assign From	LAN BOON CHIN	Assign Date	17/10/2024

2. Vehicle Details

Make & Model	YAMAHA X-MAX	C.C	250
Engine No.	G3H5E0009915	Year of Reg.	16/06/2022
Chassis No.	PMYSG4020N0000966	Colour	GREY
Odometer	62887 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	120/70-15	PIRELLI	5
L/H Front Tyre			
R/H Rear Tyre	140/70-14	PIRELLI	5
L/H Rear Tyre			

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT, REAR PORTION AND N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	17/09/2024	Inspection Date	17/10/2024
Survey held at	51 UBI AVE 1 #03-30 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934 - REPAIRER: KARZ WORKS PTE LTD		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days