



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS MS FIRST CAPITAL INSURANCE LTD	Ref:	CS/FCI24100313/Rvp3m4
16 RAFFLES QUAY	Date:	20/11/2024
#42-01 HONG LEONG BUILDING	Code:	FCI2
SINGAPORE 048581		

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8113U	Veh. Inspected	SNM 8599C
Policy No.	D-24101861MFCT	Coverage	0
Claim No.	D24009164MFCT	Excess	\$0.00
Assign From	BETTY	Assign Date	17/10/2024

### 2. Vehicle Details

Make & Model	SKODA SUPERB 2.0 L&K S/R	C.C	1984
Engine No.	DNN155723	Year of Reg.	27/10/2023
Chassis No.	TMBBM7NP2P7040173	Colour	GREEN
Odometer	11638 KM	Steering	IN ORDER
Brakes	IN ORDER	General	FAIR
Modification(s)	RIMS: SPORTS RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/40R19	BRIDGESTONE	6
L/H Front Tyre	235/40R19	BRIDGESTONE	6
R/H Rear Tyre	235/40R19	BRIDGESTONE	6
L/H Rear Tyre	235/40R19	BRIDGESTONE	6

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	16/10/2024	Inspection Date	21/10/2024
Survey held at	VOLKSWAGEN GROUP SINGAPORE PTE LTD 247 ALEXANDRA ROAD SINGAPORE 159934		

### 5a. Remarks

A)DAMAGES CONSISTENT TO ACCIDENT REPORT.  
B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days