

ASS. REC. BY:

REF: 1621Kenneth

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 240k

IDAC Accident Rpt: _____

Consistent?: Yes or No

GIA / PR Seen: _____

Consistent?: Yes or No

Est. Repairs: 2-4 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: STR 3677PYr Regn: 06, 09Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toy A171SC.C. 1598Colour M. Grey

A/C: Insured / Std / NI / NA

Sp. Reading 473 136

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: MR0538EE-106147916Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI / S/Rlm / STD / A/Rlm or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Hankook

Front

Rear

R/Bal. 6 mmR/Bal. 7 mmL/Bal. 6 mmL/Bal. 7 mmD.O.A. 11/10/24D.O.I. 4/11/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

☐

: Prel. Report

Days Of Repair: _____

☐

: Final Report

Resurvey No. of Trip: _____

Survey Fee: _____

Date/Time, File Return to?

Transportation: _____

Add Fee: ☐

: Site Insp (\$ _____)

S + RS. \$ _____

☐

: Interview (\$ _____)

: P. Insp

☐

: Tech Invs (\$ _____)

: Others

☐

: Weekend (\$ _____)

: _____

Report Format: _____

Imp Sum / I.B.I: (\$ _____)

TOTAL

来發 (明記) 摩哆有限公司

LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0035960
Chang Yong Chin Lawrence

Page 1 of 2
Your ref. TP-SH 7318X MS FC
Job No. 74765
Our ref. 24.10.15
Payment
Date 16/10/2024

Attn

NOT Withdraw
11 Sep 8
Repair After Paim
2-4 days

Vehicle No SJR 3677P
Vehicle Model : Toyota Altis
Accident on ... 11/10/2024

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
Supply of Parts:					
1.00	Pc	Rear end panel	1,134.50	25.00	850.88 <i>7</i>
1.00	Pc	Rear bumper inner retainer LH	86.20	25.00	64.65 <i>7</i>
1.00	Pc	Rear bumper outer retainer LH (No.2)	58.40	25.00	43.80 <i>7</i>
1.00	Pc	Rear bumper outer retainer LH	122.10	25.00	91.58 <i>7</i>
1.00	Pc	Rear bumper outer retainer LH	122.10	25.00	91.58 <i>7</i>
1.00	Pc	Rear bumper	1,607.70	25.00 <i>CM</i>	1,205.78 <i>✓</i>
1.00	Pc	Rear bumper absorber	216.10	25.00 <i>CM</i>	162.08 <i>✓</i>
1.00	Pc	Rear bumper absorber bracket LH	140.60	25.00 <i>n</i>	105.45 <i>X</i>
1.00	Pc	Rear bumper absorber bracket RH	140.60	25.00	105.45 <i>7</i>
4.00	Pcs	Rear bumper lower clips	4.50	25.00 <i>ne</i>	13.50 <i>✓</i>
2.00	Pcs	Rear bumper retainer clips	3.50	25.00 <i>ne</i>	5.25 <i>✓</i>
Labour & Misc:					
1.00		To cut+weld rear end panel including renew above parts	800.00		800.00 <i>7</i>
1.00		To knock and repair rear boot	250.00		250.00 <i>nn X</i>

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature:

Date:

公司拥有最先进的 CAROLINER MARK IV 机械, 可提供多种维修方式及给于快速与准确的测量方式和大铁修理外, 还有先进的 SAICO Deluxe 喷漆烘炉。

Our services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the support system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced SAICO Deluxe oven heater for re-spraying all motor vehicles."

来發 (明記) 摩哆有限公司
LAI HUAT (MENG KEE) MOTOR PTE LTD

160 Sin Ming Drive #04-01, #04-02 & #07-03 Singapore 575722 Tel: 6453 8110 Fax: 6459 6267
GST No: M2-0128609-3
UEN: 199407592C

ESTIMATE

EST. No EST0035960
Chang Yong Chin Lawrence

Page 2 of 2
Your ref. TP-SH 7318X MS FC
Job No. 74765
Our ref 24.10.15
Payment
Date 16/10/2024

Attn

Vehicle No SJR 3677P
Vehicle Model : Toyota Altis
Accident on ... 11/10/2024

11/10/2024
Both Police and Accident
11/10/2024 10:42 (SST)
Moulmein Rd, Singapore
at slip road towards CTE/Jang Mo Kio
Singapore

Quantity	Unit	Description	Unit price	Disc. pct.	Amount
1.00		To remove+refit reverse sensor	80.00		80.00 50/-
1.00		To respray paint rear end panel, rear bumper, rear boot etc	950.00		950.00 400/-

Chang Yong Chin Lawrence (Zhang Yongchin)
11/10/2024
lawrencechangyc@gmail.com
(Phone) +65-91174583

Toyota
Corolla
Altis 1.8
Private use
No - Claiming third party
Private car
Auto
1600
Petrol
22/06/2009
MR053ZEE106147916

Sub-Total 4,820.00
GST 9.00% 433.80
Total S\$ 5,253.80

同拥有最先进的 CAROLINER MARK IV 机械, 可提供给多种款式的车身及给于快速与准确的测量方式和大铁炉
还有先进的 SAICO Deluxe 喷漆烘炉。
services include the latest and reliable CAROLINER MARK IV repair bench, draw-aligner and the su
system to provide accurate re-alignment and speedy repairs. We also provide the new and advanced S
e oven heater for re-spraying all motor vehicles."



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of First Submission	11/10/2024 17:24 (SGT)
Reported by	Both Policyholder and Actual Driver
Date of Accident	11/10/2024 10:42 (SGT)
Exact Location of Accident	Moulmein Rd, Singapore
Additional Location Information	at slip road towards CTE/Ang Mo Kio
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR3677P
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	Chang Yong Chin Lawrence (Zhang Yongqin)
NRIC No	SXXXX813D
Email Address	lawrencechangyc@gmail.com
Mobile Phone No	(Phone) +65-81574583
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Corolla
Variant	Altis 1.6
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1600
Vehicle Fuel	Petrol
First Registration Date	22/06/2009
Chassis no	MR053ZEE106147916
Effective Date/Time of Ownership	-

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMPCSNA00065262403

DRIVER

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Traffic Police Department for investigation.**
6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police) for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents (including their lawyers/law firms) which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]

11/10/2024
1426hrs


[Signature]

Policyholder's Signature / Date & Time

Actual Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)

Sketch Plan



* Taxi Front bang back of my car

Time: 1042hrs

Date: 11-OCT-2024

Weather: Fair