**ASSIGNMENT** 

	The state of the s
From: Date:	Veh No: SKX 7481S Yr Regn: 2015 1 PK
Estimated Cost:	Type: M.Car / M.Cycle / Bue / Van / Lorry / Taxi / Prime Mover /
OD / TP ( WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: SkX 74815	Make: CITROEN GRANDCY PILMSS 01-6 c.c 1860
at Workshop m/s CYCLE & CARRIAGE	Colour REO A/C: insured / Std / Ni / NA
of PANSON GARDEN	Sp.Reading 14/1783 T/Radio: Insured / Std / NI / NA
Insured: FU <sup>2</sup>	Eng/No:
Policy No.	CNO: VF73ABH 2TFJ808871
Claims No.	Gen. Cand: Good / Fair Poor / Burnt
Sum Insured: Excess:	Steering: Inorder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil /S/Rim / STD A/Rim or
	Tyre Size: F: 205 60R16
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO MOKO OF
Bal. or Market Value: 20K	Front Rear
IDAC Accident Rport: Consistent?: Yes or No	R/Bai. mm R/Bai. 6 mm
GIA / PR Seen: Consistent?: Yes or No	L/Bail. 6 mm L/Bail. 6 mm
Est. Repairs: days Res.: Yes or No	D.O.A. 12/16/24 D.O.I. 05/11/24
Lum Sum: % 3 Val.: Yes or No	Survey held at PANDAN G
CA / REV / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN/OU	IT REAR OS
Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction REPAIR LIMIT - 5K	Transportation and residence of the second s
repaire civilia sk	
and the same and t	
9 - <u>-</u>	
	The second of th
Date/Time, File Pass to? : Prell. Report	Days Of Repair:
; Final Report	The same of the sa
Outs/Time, File Return to?	
z) Add Fe	Pe: Site Insp (\$ ); SARS SI
7	Interview (S
Report Format:	Tenh Inun (\$
Lump Sum / I.B.I: (\$	
Camb Sain / Par (A.	: Weekend (\$
	TOTAL



# CYCLE & CARRIAGE FRANCE PTE. LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792



#### STIMATE

Company Reg No. 200609327M GST Reg No. MR-8500111-X

Invoice Name & Address			Owner Name & Vehicle Info						
Lee Tiong Guan		Cust No/Name	/LEE	TIONG GUA	N				
,	cee fromy (	ouan		Reg No/Reg Date	SKX7481S*CPP	/ 28/12/20	15		
	31 KIM KEA			Date In/Mileage	/	0			
	#17-04 Cal			Chassis No	VF73ABHZTFJ80				
	Singapore	328882		Engine No	10JBHD3019522				
	Contact No	Mobile: 98197275					ATE CO.	IEODT	
	Contact No	MODITE: 90197275		Make/Model	CIT/GC4P 1.6			IFUKI	
				Colour/Trim	PYM	/ 8	Mŀ		
Account No	Terms	Date/Time Printed	CSE	Operator		WIP No			
CSM00077	Cash	15/10/2024/ 18:28		1015/ Vikneswara	n Naidu A	10493			
		Description of Goods	s / Services		Qty	Unit Price	Disc%	An	nount /
E PNT88000					0 15			1500	4550.00 3300.00
	RR BUMPER, NEW DAMAGED	RR TAILAGTE, REPAIR RE	RHS FENDER	R, REPAIR END PANEL,	G760+V			(320	•
E DNTOROO	n							Ma.	3300.00
SPRAY I	RR BUMPER,	TAILAGTE, RR RHS FENDE	R, END PANE	EL, RR TAILAGTE 🕡 🛭	10X3+			16-21	,590.00
GAKNISI	H LWK				, (			1950	,
A 1002890		NOCTIC CHECK ON FLECTS	ONTO CONTRO	N. CVCTEH					380.00
A 1002890		GNOSTIC CHECK ON ELECTR	CONTC CONTRC	JL SYSIEM				120	150.00
	- WIRING AND	ELECTRICAL						1	150.00
E PNT8800	0	Military							350.00
	RR WINDSCRE	EEN GLASS	-		1 -				/
E PNT8800	u LEAK TEST	The Control of the Co	C	1000	ITO				50.00
E PNT8800			OL	ıma	LC			180	280.00
		TRANSFER REAR TAILAGT							'
E PNT8800	O AND REFIT	CENCOD						(vv	150.00
M SUNDRY	AND KEFTI	SENSUR							120.00
SEALING	G WINDSCREE	N							120.00
M SUNDRY	IST DDOOFIN	ıc						100	200.00
M SUNDRY	UST PROOFIN	10						·	150.00
	BODY PNL S	SEALANT							150.00
M SUNDRY	COLAR 51	TINT							280.00
M SUNDRY	SOLAR FILM	1 1111						,	
	NUMBER PLA	ATE						<b>X</b>	120.00
M SUNDRY								10	90/00
	CNC BADGE							ر ر	9.00
M SUNDRY SUNDRIE	FS							20	88.00
	UMPER CAL	/						_	
M KEAR BI	DIFFER C				1.00	1634.00	0.00		

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur. We would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit care or chaque. Too must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber small or other repair requiring



## **CYCLE & CARRIAGE FRANCE PTE. LIMITED** PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens, Singapore 609339 Tel: (65) 64792792



#### ESTIMATE

Company Reg No. 200609327M GST Reg No. MR-8500111-X

	Inve	oice Name & Address		Owner N	ame & Vehicle I	nfo	g No. MR-8500111-X
1	_ee Tiong (	Guan	Cust No/Nam	e /LE	E TIONG GUAN		
•	ice frong (	Juan	Reg No/Reg	Date SKX7481S*CP	P/ 28/12/2015	5	
	31 KIM KEA		Date In/Milea	ge /	0		
	#17-04 Cala		Chassis No	VF73ABHZTFJ	808871		
	Singapore :	328882	Engine No	10JBHD30195	22		
	Contact No.	Mobile: 98197275	Make/Model		6 BLUEHDI EA	T6 CONFOR	т
,	Contact No	MODITE: 9619/2/5	Colour/Trim	PYM	/ 8M		
Account No	Terms	Date/Time Printed	CSE Operator		WIP No		
CSM00077	Cash	15/10/2024/ 18:28		neswaran Naidu A	10493		
C31100077	Cusii	Description of Good		Qty	Unit Price	Disc%	Amount
M BUMPER	BRACKET ?	-		1.00	691.00	0.00	691.00
M BUMPER	SKIRT CA		1/paul	1.00	539.00	0.00	539.00
M RECESS	DOOR X		CHINA	1.00	105.00	0.00	105.00
M BRACKET	SET		Hp Fire	1.00	233.00	0.00	233.00
	SET LATA		th 2000	<b>v868</b> 1.00	233.00	0.00	233.00 65.00
	SEAL /	. /	' ,	1.00	65.00	0.00	491.00
	BRACKET	K /	L Na	1.00	491.00	0.00	82.00
	ATE C		0,000	1.00	82.00 220.00	0.00	220.00
	IER LH			1.00 1.00	220.00	0.00	220.00
	IER RH		92/11/3	1.00	2988.00	0.00	2988.00
M TICT EV	TE CAL /	n/_		1.00	569.00	0.00	569.00
M WEATHED	STRIP PAVI	110N 7		1.00	128.00	0.00	128.00
M TATICAT	E GLASS A	of the	1/2 6X	1.00	398.00	0.00	398.00
	RIVET		0 42	10.00	13.00	0.00	130.00
	STRIP A		Pari	1.00	212.00	0.00	212.00
M BADGE	-/		1	1.00	91.00	0.00	91.00
M BADGE			**	1.00	91.00	0.00	91.00
M BADGE				1.00	114.00	0.00	114.00
M TAIL-LI	GHT LH X			1.00	502.00	0.00	502.00
M TAIL-LI	GHT RH	0		1.00	480.00	0.00	480.00
		PLEMENTAIRE '.		1.00	199.00	0.00	199.00
		PLEMENTAIRE 7.		1.00	224.00	0.00	224.00
M SENSOR				1.00	389.00	0.00	389.00
M SENSOR				1.00	228.00	0.00	228.00
M ASSIST.	CAMERA .			1.00	433.00	0.00	433.00
		the Repairer	nsultants hence notify of the following:	7			
			fore/after spray painting				
			aged part(s) during resurvey				
			subject to confirmation				
			vey is on a "Without Prejudice" basis				
Confirm &	accepted by	<ul> <li>No illegal mod</li> </ul>	fication(s) is allowed	Parts			11,689.00
		<ul> <li>Supplementary</li> </ul>	item(s) must be resurveyed and	Labour			9,220.00
		is subject to fir	al approval from Insurance Compan	Standard	Menu		0.0
				Specialis	t Job		0.00
		Acknowledged b	y Repairer	Diagnosti			0.00
Authorized	signatory and	d company stant)		Sundry/Ot	hers		1,030.00
	J , all			Total (w/c			21,939.00

ate of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

# m.sgcarmart.com













# Citroen Grand C4 Picasso Diesel 1.6A e-**HDi**

**\$17,800** Instalment \$1,410/mth



□ Loan Calculator



### Overview Photo Research

Depreciation

(i) \$12,600 / year

Reg. Date

16-Sep-2015 (10mths 9days COE left)

Manufactured

2015

Mileage

Auto

**Engine Cap** 

Transmission

1,560 cc

Road Tax

(i) \$1,144 / year

Power

85.0 kW (113 bhp) View specs of the Citroen Grand C4 Picasso Diesel (2014-2017)

Curb Weight

① 1,320 kg

\$57,089

**Fuel Type** 

Diesel (Euro 5 Engine and Above)

COE

**ARF** 

OMV \$26,419

\$13,987

Dereg Value

\$11,889

### > Back to OneMotoring

### **Enquire PARF/COE Rebate for Registered Vehicle**

/ehicle Owner Particulars		
Owner ID Type:	Singapore NRIC	
Owner ID:	622F	
/ehicle Details		
/ehicle No.:	SKX7481S	
/ehicle to be Exported:	No	
ntended Deregistration Date:	06 Nov 2024	
/ehicle Make:	CITROEN	
/ehicle Model:	GRAND C4 PICASSO 1.6 BLUEHDI EAT6 S/R	
Primary Colour:	Red	
Manufacturing Year:	2015	
ingine No.:	10JBHD3019522	
Chassis No.:	VF73ABHZTFJ808871	
Maximum Power Output:	88.0 kW (118 bhp)	
Open Market Value:	\$26,295.00	
Original Registration Date:	28 Dec 2015	
irst Registration Date:	28 Dec 2015	
ransfer Count:	0	
Actual ARF Paid:	\$13,813.00	
ntended PARF Rebate Details		
PARF Eligibility:	Yes	
PARF Eligibility Expiry Date:	27 Dec 2025	
PARF Rebate Amount: ntended COE Rebate Details	\$7,597.00	
COE Expiry Date:	27 Dec 2025	
COE Category:	A - Car up to 1600cc & 97kW (130bhp)	
COE Period(Years):	10	
QP Paid:	\$59,200.00	
COE Rebate Amount:	\$6,747.00	
Total Rebate Amount:	\$14,344.00	
Message		

The information contained herein is correct as at 06 Nov 2024