

## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile MS INCOME INSURANCE LTD Ref: CS/INC24100321/Anh3m4 75 BRAS BASAH ROAD Date: 26/12/2024 **INCOME CENTRE SINGAPORE 189557** Code: INC 1. **Policy Particulars :- THIRD PARTY CLAIM** Insured Veh. SKW 4626S Veh. Inspected **SLS 9501U** Policy No. Coverage 0 Claim No. MT/1300288-001 **Excess** \$0.00 **Assign From** JEFF LIN **Assign Date** 18/10/2024 2. **Vehicle Details** C.C Make & Model HYUNDAI AE IONIQ 1580 Engine No. G4LEHU424077 Year of Reg. 12/10/2017 Chassis No. KMHC851CVHU040999 **BLACK** Colour Odometer 152768 KM IN ORDER Steering **Brakes** IN ORDER GOOD General Modification(s) RIMS: SPORTS RIM **Conditions of Tyres** 3. Size Make Balance (mm) 225/45R17 **BRIDGESTONE R/H Front Tyre** 6 6 L/H Front Tyre 225/45R17 **BRIDGESTONE** 6 R/H Rear Tyre 225/45R17 **BRIDGESTONE BRIDGESTONE** 6 L/H Rear Tyre 225/45R17 **Description of Damages** THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. 5. **General Information** Inspection Date **Accident Date** 17/10/2024 18/10/2024 (13:31) Survey held at HD PERFECT AUTOWORK PTE LTD 8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875 5a. Remarks A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. **Estimate Days of Repair** 

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days