# **SINGAPORE ACCIDENT STATEMENT**

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

  4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of the insurance companies.
   5. Any false reporting may be referred to the Police for investigation.
   6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

## **ACCIDENT STATEMENT**

Date of First Submission 17/10/2024 12:20 (SGT) Reported by **Actual Driver** Date of Accident 17/10/2024 06:50 (SGT) Exact Location of Accident Marymount Rd, Singapore Additional Location Information Country/State of Loss Singapore

## **DETAILS OF OWN VEHICLE**

Toyota

JTDKB3FU503097306

Vehicle Registration Number SH9877K

INSURED/POLICYHOLDER

Is company? Yes Name Of Registered Owner COMFORT TRANSPORTATION PTE LTD Company Reg No 199303821R Email Address fleetsafety@cdgtaxi.com.sg Mobile Phone No (Phone) +65-97682301 Alternative Phone No (Office) +65-65508768

#### VEHICLE PARTICULARS

Manufacturer

Model Prius Variant 5DR HATCHBACK (AUTO)(2WD) Exact purpose for which vehicle was being used at time of accident Private hire Are you claiming under your own insurance policy for repair to No - Claiming third party your vehicle? Vehicle Category Taxi Transmission Auto CC 1798 Vehicle Fuel Petrol-Electric First Regisration Date

INSURANCE COMPANY

Name of Insurance Company MS First Capital Insurance Ltd Policy Number / Cover Note Number D-24101861MFCT

DRIVER

Chassis no

Effective Date/Time of Ownership

Name of Driver NRIC No Date Of Birth Occupation Driving Pass Date Driving License Pass Class Driving License Validity Driving experience Gender Mobile Number Alt. Phone Number Email Address Address Address Address complement Postcode Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicle Owned by Driver	LI WEI TENG \$1774345G 31/12/1966 Outdoor 07/06/1985 3 Valid 39 YEARS AND 4 MONTHS Male (Phone) +65-97682301 - fleetsafety@cdgtaxi.com.sg BLK 220A SUMANG LANE # 09 - 79 - 821220 No Hirer No	
Insurance Company of Other Vehicle Owned by Driver	-	
GENERAL INFORMATION OF THE ACCIDENT		
Type of Accident Weather Conditions Road Surface	Collision - Change/cross lane Clear Dry	
OTHER INFORMATION		
Was any foreign vehicle involved in the accident?  Number of vehicles involved in the accident  Was anybody injured in the Accident?  Was any injured conveyed to hospital by ambulance?  Was any other vehicle or property damaged?  Number of Passengers (Including Driver)  Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?  Translator's name  Translator's ID  Translator's phone number  Translator's email  Original language used in the statement	-	
Name Gender	UNKNOWN Female	
DETAILS OF POLICE ACTION		
Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom?	No No	
CIRCUMSTANCES OF ACCIDENT		
ON 17.10.2024 AT ABOUT 0650HRS VEHICLE A SH9877K WAS ALONG MARYMOUNT ROAD. AFTER BISHAN STREET 22, VEHICLE B SNH8664Z ON MY LEFT DROVE CLOSE TO VEHICLE A. VEHICLE B RIGHT FRONT SIDE SWIPE VEHICLE A LEFT FRONT DOOR. PASSENGER IS NOT INJURED AND I PROCEEDED TO SEND HER TO DESTINATION AT SHUNFU. SCENE PHOTOS AND HANDPHONE TAKEN		

Yes

C Accident report SA1K24AH000B

Are accident photos available for attachment?

ATTACHMENT(S)

Was there any video captured by Car Camera? Yes
Reasons for not uploading a video of the accident FILE IS NOT SUITABLE

## **DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number SNH8664Z Vehicle Manufacturer Toyota Vehicle Model LEXUS RC F COUPE Vehicle Variant Vehicle Colour Vehicle Category Private car Name of Driver Contact Number (Phone) +65-96637312 Address Address complement Postcode Insurance Company Name Nature Of Damage RIGHT FRONT Details of property damaged in accident No. Of Passenger (Including Driver) 2

#### SKETCH PLAN

## IMPORTANT NOTICE

- 1. Please correctly report the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorized Driver.
- 3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the center and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims
- (ii) investigating the accident and/or my claims.
- (ii) carrying out and/or dealing with my instructions or responding to any enquiries by me.
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(Collectively the "Purposes")

- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third-party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


Policyholder's Signature / Date &

Driver's Signature (If driver is not the policyholder) / Date & Time 17.10.2024. 0930HRS

Witnessed by Reporting Centre Personnel

## Sketch Plan

Time



## Describe Circumstances of the Accident

ON 17.10.2024 AT ABOUT 0650HRS VEHICLE A SH9877K WAS ALONG MARYMOUNT ROAD. AFTER BISHAN STREET 22, VEHICLE B SNH8664Z ON MY LEFT DROVE CLOSE TO VEHICLE A. VEHICLE B RIGHT FRONT SIDE SWIPE VEHICLE A LEFT FRONT DOOR. PASSENGER IS NOT INJURED AND I PROCEEDED TO SEND HER TO DESTINATION AT SHUNFU. SCENE PHOTOS AND HANDPHONE TAKEN	

## Declaration

I/We declare the foregoing particulars are true in every respec

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time 17.10.2024.

0930HRS

Witnessed by Reporting Centre Personnel



